

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003193/UQGA3Q2
Date: 18/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100468581
Claimant Vehicle No :	SGJ82C	Insured Vehicle No :	SLC4660K
Date of Loss:	06/03/2021	Nature of Claim:	TP
		Claim No:	4226515129SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGJ82C	Engine No:	CZA008903
Make & Model:	BENTLEY BENTAYGA V8, 4.0 D S/R 5 SEATER (A)	Chassis No:	SJAAE14V2JC018714
Reg. Date:	01/08/2017 (Man. Year: 2017)	Odometer:	21044 km
Colour:	White		
Engine Capacity:	3956 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	285/45 R21	Rear Tyre Size:	285/45 R21
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	87,511.50	19,352.13	68,159.37	77.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,050.00	2,970.00	73.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	91,531.50	20,402.13	71,129.37	77.71
+ GST 7.00/7.00% (S\$)	6,407.21	1,428.15	4,979.06	77.71

Nett Amount (S\$)	97,938.71	21,830.28	76,108.43	77.71
+ Loss of Use (5.0 x S\$150.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		22,587.73		
Global Sum Settlement (S\$)		22,550.00		

INSPECTION

Date of Assignment: 10/03/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 3.0 days

Inspected At:

My Car Consultant Pte Ltd (HQ)
 60 Jalan Lam Huat,, Carros Centre #05-67/68
 Singapore 737869

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	16,124.50 F	*14,849.94 FL
2	1		*REAR BUMPER LOWER	Not Necessary	8,142.00 F	*- FL
3	1		*REAR BUMPER DIFFUSER	Crumpled	5,814.00 F	*5,114.94 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	354.00 F	*- FL
5	1		*REAR BUMPER LOWER LAMP	Not Necessary	1,159.00 F	*- FL
6	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	512.00 F	*- FL
7	1		*REAR BUMPER CHROME (CENTRE)	Crumpled	698.00 F	*698.00 FL
8	1		*REAR BUMPER CHROME (SIDE)	N/S Scratched	796.00 F	*398.00 FL
9	1		*REAR BUMPER TOWING COVER	Not Necessary	112.00 F	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Repair	3,215.00 F	*- FL
11	2		*REAR BUMPER SIDE RETAINER	Not Necessary	580.00 F	*- FL
12	1		*REAR BUMPER REVERSE SENSOR	N/S Shorted	1,948.00 F	*408.15 FL
13	1		*TAILGATE	Not Necessary	24,879.00 F	*- FL
14	1		*TAILGATE LOGO	Not Necessary	321.00 F	*- FL
15	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	741.00 F	*- FL
16	1		*TAILGATE WEATHERSTRIP	Not Necessary	487.00 F	*- FL
17	1		*TAILGATE LOCK	Not Necessary	1,025.00 F	*- FL
18	1		*SET TAILGATE WINDSCREEN MOULDING	Not Necessary	589.00 F	*- FL
19	1		*REAR END PANEL	Repair	3,587.00 F	*- FL
20	1		*REAR END PANEL TOP GARNISH	Not Necessary	758.00 F	*- FL
21	2		*REAR EXHAUST CHROME PIPE	Not Necessary	2,030.00 F	*- FL
22	1		*REAR EXHAUST PIPE	Not Necessary	12,874.00 F	*- FL
23	2		*REAR EXHAUST MOUNTING	Not Necessary	136.00 F	*- FL
24	1		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
25	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
26	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	150.00 FS	*- FS
27	1		*SET TAILGATE OUTER MOULDING CLIPS	Not Necessary	80.00 FS	*- FS
28	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
30	1		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	87,511.50	21,499.03
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,146.90
Total Parts (\$\$)	87,511.50	19,352.13

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
2	REMOVE AND REFIT REAR SEAT ,UPHOLSTERY	New	300.00	0.00
3	REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND REFIT REAR EXHAUST SYSTEM	New	150.00	0.00
5	REMOVE AND REFIT TAILGATE MECHANISM	New	150.00	0.00
6	TUFF COAT	New	150.00	0.00
7	PANEL BEATING ON AFFECTED AREA	New	1,500.00	500.00
8	SPRAY ON AFFECTED AREA	New	1,500.00	500.00
Gross Labour Cost (S\$)			4,020.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >