



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTF 6797

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>					
1	TAIL LAMP	CUT	275.00	-	220.00
1	REAR FENDER	SCRATCHED	118.00	-	118.00
1	COVER R/H TOP	CUT	180.00	-	180.00
1	COVER R/H LOWER	CUT	175.00	-	175.00
1	SIDE COVER R/H	CUT	275.00	-	185.00
1	EXHAUST COVER	CUT	115.00	-	55.00
1	PILLION BRACKET	NOT NECESSARY	175.00	-	-
1	BRAKE LEVER	CUT	65.00	-	25.00
1	BALANCER R/H	CUT	35.00	-	15.00
1	FOOT REST R/H	NOT NECESSARY	65.00	-	-
1	MIRROR R/H	NOT NECESSARY	140.00	-	-
1	SIGNAL FRONT R/H	CRACKED	190.00	-	148.00
1	FRONT FENDER	NOT NECESSARY	230.00	-	-
1	TAIL COVER	CUT	95.00	-	55.00
	LESS 10% DISCOUNT		-	-	-117.60
			2,133.00	-	1,058.40
<u>SPECIAL NETT ITEMS</u>					
1	NO PLATE (SN)	BENT	20.00	-	10.00
			20.00	-	10.00
<u>LABOUR</u>					
	WORKMANSHIP.STRIP FIX BODY PARTS.		280.00	-	200.00
	TOWING SERVICE.	NOT NECESSARY	60.00	-	-
			340.00	-	200.00
GRAND TOTAL			2,493.00	-	1,268.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00
---	--	--	-----------------

Report Ref No. CS/AGI21003215/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.