

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM21003217/Rtf3e2	
	8 SHENTON WAY AXA TOWERSING		Date:	04/02/2022	
	ATTN: TAN JUN H	ONG	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SHA 2204R	Veh. Inspected	JNF 7614	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S1M034AW	Excess (\$)	0.00	
	Assign From	TAN JUN HONG	Assign Date	11/03/2021	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA 135LC	c.c	135	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	PMYKG0550B0012082	Colour	WHITE	
	Odometer	66185 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	70/90-17	MAXXIS	3 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	80/90-17	MAXXIS	3 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	26/02/2021	Inspection Date	20/10/2021	
	Survey held at	urvey held at KENG HOCK MOTOR			
		188 YIO CHU KANG ROAD, SINGAPORE 545635			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				