M. V. = ? ?

8 ASSESSMENT OF DAMAGE AND COSTS

Report no:

93M0321.KHM

Vehicle no:

JNF7614

A SPARE PARTS

THE PARTS				
Deserver		Assessed	Repairer's	Revised
Pront fender Description	Qt		Amount	Amount
RH front leg shield	1		58.00	58.00
KH air grille	1	broken	95.00	95.00
LH front leg shield	1	broken	40.00	40.00
Headlamp base panel	1	cracked	95.00	
LH side centre cover	1	broken		95.00
RH side centre cover	1	scraped	58.00	36.00
KH rear side board	1	broken	55.00	55.00
Handlebar xeve	1	broken	55.00	55.00
SET = 2PCS Handlebar end balancer co.	1	bent	85.00	85.00
Brake lever	1	abraded	55.00	55.00 X
Mirror set	1	abraded/bent	36.00	36.00 x ✓ ८० ००
Front fork assy L/R	1	scraped	18.00	18.00
Steering stem	2	bent/scraped	58.00	58.00 Local 1974
Steering con/bearing set – upper	1	bent/distorted	594.00	594.00 X & 8
Steering con/bearing set - upper	1	necessary	185.00	185.00X5VC
Front brake disc xsvc	1	necessary	36.00	36.00
Front brake caliper assy xsvc	1	bent/distorted	42.00	42.00
Front rim	1	abraded	115.00	115.00 x
Front rim axle bolt	1	to repair	150.00	150.00 x
Radiator assy	1	bent	295.00	SN \$100.00 50
Front frame inner cover (black)	1	bent/distorted	35.00	35.00
Front footrest bar	1	cracked	228.00	228.00
Front footrast our	1	bent/distorted	80.00	80.00
Front footrest assy RH	1	bent	52.00	52.00
Rear suspension swing arm xsvc	1	bent/distorted	35.00	35.00
Rear suspension swing arm bush xsvc	1	necessary	255.00	255.00 x
Webi Tilli	1		35.00	
Exhaust pipe assy	1	to repair	290.00	35.00 x
Exhaust pipe front cover	-	abraded/dented/bent	280.00	SN \$100.00 50
Exhaust pipe protection cover	1	dented/abraded	35.00	280.00
Exhaust pipe end cap	1	abraded		35.00
	1	abraded	45.00	45.00
		Subtotal of the above	28.00	28.00
(Special nett)		Discount 10%	3,523.00	2,938.00 2292
		Subtotal 1:	352.30	293.80
Add SN items above			3,170.70	2,644.20 2062.80
Front sticker number plate set	1	200000	la	bour-200.00 200 100
Kadiator grille		necessary	30.00	30.00 10
Radiator coolant		bent/distorted	45.00	
Rear box		necessary	15.00	45.00 30 20
Rear box rack xsvc	1	dislodged/missing		15.00 10
TOOL BOX 18CV X2AC		bent	195.00	195.00 150
		Subtotal 2:	125.00	125.00 x
			410.00	
	•	Total cost of parts:	3,580.70	3,254.20
B LABOUR				3,234.20
T				

Towing fee (2x)

Report no:

93M0321.KHM

Vehicle no:

JNF7614

Labour for dismantle and remove all damaged parts, renew and install new

600.00

500.00 350

parts.

To check wiring.

30.00

20.00

Total cost of labour:

700.00	580.00
--------	--------

370

Total cost of repair:

4,280.70 3,834.20

7 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is

\$3,834.20

(a) The recommended cost of repair based on lump sum repairs would be

\$3,100.00

(b) The estimated number of days for the repairs would be

Seven (7)

(1st Re-inspection conducted on 28 May 2021) (Post Repir Inspection conducted on 6 July 2021)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its preaccident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Yours faithfully

Liaw Leong San

Licensed Automotive Appraiser

Dated:

28 July 2021

200,00 200,00 37,00 20% 29% L(S-\$2,300/5 DAYS