

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS21003219/GVF3E2

Date: 25/03/2021

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	FBP2698R	Insured Vehicle No :	SKR6872K
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP2698R	Engine No:	G3J6E0176225
Make & Model:	YAMAHA FZ150, 150cc	Chassis No:	MH3RG4710KK093899
Reg. Date:	04/03/2019 (Man. Year: 2019)	Odometer:	7690 km
Colour:	Black		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80-17	Rear Tyre Size:	140/70-17
Front Left Side:	IRC 5 mm	Rear Left Side:	IRC 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	469.00	422.10	46.90	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	250.00	100.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	819.00	672.10	146.90	17.94
+ GST 7.00/7.00% (S\$)	57.33	47.05	10.28	17.93
Nett Amount (S\$)	876.33	719.15	157.18	17.94

INSPECTION

Date of Assignment:	11/03/2021		
Date Inspected:	11/03/2021	Inspected At:	Atan Motoring Supply Pte Ltd (HQ) Block 3006 Ubi Road 1, #01-368/370 Singapore 408700
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2021)	
Parts:	N/A	YAMAHA FZ150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP2698R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GEAR LEVER	Broken	55.00 F	*55.00 FL
2	1		*LEFT SIGNAL	Cut	30.00 F	*30.00 FL
3	1		*CLUTCH LEVER	Bent	18.00 F	*18.00 FL
4	1		*BALANCER	Cut	8.00 F	*8.00 FL
5	1		*SIDE STAND	Bent	38.00 F	*38.00 FL
6	1		*HANDLE BAR	Bent	85.00 F	*85.00 FL
7	1		*LEFT REAR SIDE COVER	Cut	65.00 F	*65.00 FL
8	1		*LEFT SIDE MIRROR	Cut	55.00 F	*55.00 FL
9	1		*NUMBER PLATE LAMP	Distorted	25.00 F	*25.00 FL
10	1		*REAR NUMBER PLATE REFLECTOR	Cracked	25.00 F	*25.00 FL
11	2		*REAR MUDGUARD	Broken	65.00 F	*65.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	469.00	469.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	46.90
Total Parts (\$\$)	469.00	422.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	FORK ALIGNMENT	New	120.00	120.00
2	TPT TO IDAC TO WORKSHOP	New	80.00	0.00
3	LABOUR	New	150.00	130.00
Gross Labour Cost (S\$)			350.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >