

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21003229/R1BS3Q2
Date: 10/05/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBH5256E	Insured Vehicle No :	SLT3892A
Date of Loss:	04/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0000990

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH5256E		
Make & Model:	BAJAJ PULSAR, 150cc DTS-i (M)	Engine No:	JLZCDC85408
Reg. Date:	08/07/2013 (Man. Year: 2013)	Chassis No:	MD2A36FZ8DCC89361
Colour:	Multi-colour	Odometer:	96332 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,475.00	3,358.50	3,116.50	48.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,405.00	595.00	810.00	57.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,880.00	3,953.50	3,926.50	49.83
Approved Total (Overridden) (S\$)		3,150.00		

Nett Amount (S\$)	7,880.00	3,150.00	4,730.00	60.03
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
Nett Liability (S\$)		3,270.00		
Global Sum Settlement (S\$)		3,200.00		

INSPECTION

Date of Assignment: 11/03/2021

Date Inspected: 12/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Hkl Lim Team Motorsport (HQ)
 BLK 1008 #01-24 BUKIT MERAH LANE 3
 Singapore 159722

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Apr 2021)	
Parts:	N/A	BAJAJ PULSAR 150cc DTS-i (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH5256E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*METER ASSY	Serviceable	450.00 F	*- FL
2	2		*FRONT FORK ASSY LH/RH	Bent	650.00 F	*650.00 FL
3	1		*FRONT FORK UNDER BRACKET	Bent	220.00 F	*220.00 FL
4	1		*STEERING CONE BEARING	Necessary	90.00 F	*90.00 FL
5	1		*FRONT FENDER	Scratched	150.00 F	*150.00 FL
6	1		*FRONT WHEEL RIM	Repair	380.00 F	*- FL
7	1		*FRONT WHEEL SHAFT	Scratched	35.00 F	*35.00 FL
8	2		*FRONT WHEEL BEARING	Necessary	40.00 F	*40.00 FL
9	1		*FRONT WHEEL BEARING OIL SEAL	Necessary	15.00 F	*15.00 FL
10	1		*FRONT BRAKE DISC	Serviceable	220.00 F	*- FL
11	1		*FRONT BRAKE CALIPER	Serviceable	250.00 F	*- FL
12	1		*HEAD COWLING LH/RH	N/S Serviceable /O/SScratched	180.00 F	*90.00 FL
13	2		*FRONT SIGNALS LH/RH	Serviceable	120.00 F	*- FL
14	1		*IU UNIT	Serviceable	170.00 F	*- FL
15	1		*IU UNIT BRACKET	Serviceable	35.00 F	*- FL
16	1		*HANDLE BBAR RH	Serviceable	120.00 F	*- FL
17	1		*HANDLE BBAR GRIP	Cut	40.00 F	*40.00 FL
18	1		*HANDLE BBAR BALANCER	Scratched	120.00 F	*120.00 FL
19	1		*WINDSHIELD	Serviceable	80.00 F	*- FL
20	1		*FRONT NO PLATE	Bent	15.00 F	*15.00 FL
21	1		*BRAKE LEVER	Scratched	45.00 F	*45.00 FL
22	1		*SIDE MIRROR LH /RH	N/S Serviceable /O/SScratched	160.00 F	*80.00 FL
23	1		*HEADLIGHT	Scratched	320.00 F	*320.00 FL
24	1		*HEADLIGHT PANEL	Serviceable	80.00 F	*- FL
25	1		*FRONT BRAKE PUMP ASSY	Serviceable	220.00 F	*- FL
26	1		*FRONT FENDER BRACKET	Bent	55.00 F	*55.00 FL
27	1		*SET CRASHBAR	Scratched	280.00 F	*280.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*CRASHBAR CLOTH	Cut	60.00 F	*60.00 FL
29	1		*BRAKE PEDAL	Scratched	70.00 F	*70.00 FL
30	1		*FRONT FOOT REST RH	Distorted	45.00 F	*45.00 FL
31	1		*FRONT FOOT REST BRACKET RH	Bent	120.00 F	*120.00 FL
32	1		*FUEL TANK COVER	Repair	250.00 F	*- FL
33	1		*TOP BOX	Scratched	350.00 FS	*150.00 FS
34	1		*REAR FOOT REST RH	Missing	45.00 F	*45.00 FL
35	1		*REAR NO PLATE (Not Necessary)	Not Consistent With The Impact	15.00 F	*- FL
36	1		*RADIATOR	Bent	320.00 F	*320.00 FL
37	1		*FORK TOP CRAM	Bent	150.00 F	*150.00 FL
38	1		*HORN	Bent	120.00 F	*120.00 FL
39	1		*FRONT BRAKE MASTER PUMP	Not Working	180.00 F	*180.00 FL
40	1		*TROTTLER CABLE	Cut	60.00 F	*60.00 FL
41	1		*COOLANT	Necessary	35.00 F	*35.00 FL
42	1		*REAR LH FOOT BRACKET	Cracked	95.00 F	*95.00 FL
43	1		*CRASHBAR SCREW	Broken	20.00 F	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,475.00	3,715.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	356.50
Total Parts (\$)	6,475.00	3,358.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY FRAME ALIGNMENT	New	680.00	250.00
2	TOWING	New	45.00	45.00
3	LABOUR	New	680.00	300.00
Gross Labour Cost (\$\$)			1,405.00	595.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >