



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

CTI

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ng Boon Leong(huang Wenliang)	Cust No/Name /NG BOON LEONG(HUANG WENLIANG)
10A JALAN LENGKOK SEMBAWANG	Reg No/Reg Date SLR2889C*KC17/ 08/08/201
SINGAPORE 759250	Date In/Mileage / 0
Contact No Mobile: 98249268	Chassis No KNAFZ411MJ5736956
	Engine No G4FGHH678487
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/03/2021/ 12:10	Bod	261 / Edwin Caina	30131			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , RR END PNL & BOOTLID REPAIR RE-ALIGN RR FLR PNL , LHR FENDER & RHR FENDER					1280			3200.00
E PNT98000 RESPRAY RR BUMPER , BOOTLID , BOOTLID SPOILER , RR END PNL , RR FLR PNL , LHR FENDER & RHR FENDER					1100			2450.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT								320.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET								320.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								280.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING								80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								100.00
M SUNDRY SUPPLY REVERSE SENSOR								280.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					40			120.00
M SUNDRY SUPPLY BODY PNL SEALANT					40			80.00
M SUNDRY SUPPLY C&C BADGE					40			50.00
M SUNDRY Sundries					20			50.00
COVER-RR BUMPER					1.00	688.00	00.00	688.00
COVER-RR BUMPER,CTR					1.00	315.00	00.00	315.00
BEAM-RR BUMPER					1.00	318.00	00.00	318.00
STAY-RR BUMPER LH					1.00	120.00	00.00	120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ng Boon Leong(huang Wenliang)	Cust No/Name /NG BOON LEONG(HUANG WENLIANG)
10A JALAN LENGKOK SEMBAWANG	Reg No/Reg Date SLR2889C*KC17/ 08/08/201
SINGAPORE 759250	Date In/Mileage / 0
Contact No Mobile: 98249268	Chassis No KNAFZ411MJ5736956
	Engine No G4FGHH678487
	Make/Model KIA/CERATO K3 1.6 A SX SR
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/03/2021/ 12:10	Bod	261 / Edwin Caina	30131			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	STAY-RR BUMPER RH	X NM			1.00	120.00	00.00	120.00
M	ANTENNA ASSY-SMARTKEY	X NM			1.00	69.00	00.00	69.00
M	BRACKET-RR BEAM LWR MTG	X NM			2.00	5.00	00.00	10.00
M	BRACKET-RR BEAM LWR,CTR	X NM			1.00	5.00	00.00	5.00
M	BRACKET-RR BEAM UPR MTG	X NM			1.00	3.00	00.00	3.00
M	BRACKET-RR BEAM UPR MTG,RH	X NM			1.00	3.00	00.00	3.00
M	GUARD-BUMPER REAR,RH	X NM			1.00	17.00	00.00	17.00
M	BRACKET-RR BUMPER SIDE MTG,LH	X NM			1.00	29.00	00.00	29.00
M	BRACKET-RR BUMPER SIDE MTG,RH	X NM			1.00	29.00	00.00	29.00
M	WIRING HARNESS-BWS EXT	X NM			1.00	216.00	00.00	216.00
M	ULTRASONIC SENSOR ASSY-P.A.	X NM			1.00	177.00	00.00	177.00
M	PANEL ASSY-TRUNK LID	X NM			1.00	1365.00	00.00	1365.00
M	HINGE ASSY-TRUNK LID,LH	X NM			1.00	68.00	00.00	68.00
M	HINGE ASSY-TRUNK LID,RH	X NM			1.00	68.00	00.00	68.00
M	LOGO ASSY-KIA SUB	X NM			1.00	37.00	00.00	37.00
M	EMBLEM-CERATO	X NM			1.00	35.00	00.00	35.00
M	PANEL ASSY-BACK	X NM			1.00	324.00	00.00	324.00
M	LATCH ASSY-TRUNK LID	X NM			1.00	112.00	00.00	112.00
M	STRIKER ASSY-TRUNK LID	X NM			1.00	18.00	00.00	18.00

SURVEYOR NAME: Steve (LKK) 17/5/21, 12:45pm
 SURVEYOR SIGNATURE: [Signature]
 DATE: 6 May 21
 REMARKS: P/P [Signature]

Confirmed & accepted by LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 Authorized signatory and company stamp

7% GST on 11526.00
 Total Payable 12,332.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal on other repair requiring the removal of the windscreen.