

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21003243/UQD3E2

**Date:** 01/04/2021

### REFERENCE

Insured/Claimant:	LOH KHOON HUNG	Policy No:	1900259720		
Date of Loss:	29/01/2021	Nature of Claim:	OD	Claim No:	9002204913SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR1327C		
Make & Model:	MERCEDES-BENZ GLA180, 1.6 (A)	Engine No:	27091031931369
Reg. Date:	20/12/2019 (Man. Year: 2019)	Chassis No:	WDC1569422J677571
Colour:	Silver	Odometer:	22933 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,131.00	1,340.59	2,790.41	67.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	780.00	820.00	51.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,731.00</b>	<b>2,120.59</b>	<b>3,610.41</b>	<b>63.00</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,120.58</b>		
<b>(S\$)</b>	5,731.00	2,120.58	3,610.42	63.00
<b>+ GST 7.00/7.00% (S\$)</b>	401.17	148.44	252.73	63.00
<b>Nett Amount (S\$)</b>	<b>6,132.17</b>	<b>2,269.02</b>	<b>3,863.15</b>	<b>63.00</b>

### INSPECTION

Date of Assignment:	11/03/2021		
Date Inspected:	12/03/2021	Inspected At:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	2.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Dented / Deformed	1,486.00 F	*1,312.45 FN
2	1		*SET FRONT BUMPER CLIPS & RIVET	Necessary	70.00 F	*40.00 FN
3	1		*FRONT BUMPER LOWER GRILLE	Cracked	152.00 F	*137.09 FN
4	1		*FRONT BUMPER LOWER GRILLE GARNISH	Repair	866.00 F	*- FN
5	1		*FRONT GRILLE ASSY	Not Necessary	1,557.00 F	*- FN
					Sub Total (\$\$)	4,131.00 1,489.54
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 148.95
					Total Parts (\$\$)	4,131.00 1,340.59

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OUT, RENEW, KNOCKING & WELDING FRONT SUPPORT PANEL, REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY INCLUDING RESET & REPROGRAMME	New	780.00	380.00
2	DIAGNOSTIC & RESET	New	300.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	480.00	380.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	40.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>1,600.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >