3/14/22, 2:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21003253/GQF3N2

14/03/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNA00023982001

Claimant Vehicle No:

PC3806S

Insured Vehicle No:

GBG2535A

Date of Loss:

02/03/2021

Nature of Claim: TP

Claim SNM21D201223/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

PC3806S Reg No:

TOYOTA HIACE, 3.0 COMMUTER GL (A) Make & Model: Engine No: 1KD2544896 Reg. Date: 01/09/2015 (Man. Year: 2015) Chassis No: KDH2230025069 Odometer: Colour: White 354093 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15 Front Left Side: Rear Left Side: Triangle 6 mm Triangle 6 mm Front Right Side: Rear Right Side: Triangle 6 mm Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,325.50	2,115.50	3,210.00	60.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	430.00	2,320.00	84.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,075.50	2,545.50	5,530.00	68.48
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	8,075.50	2,000.00	6,075.50	75.23
+ GST 7.00/7.00% (S\$)	565.29	140.00	425.29	75.23
Nett Amount (S\$)	8,640.79	2,140.00	6,500.79	75.23

INSPECTION

Date of Assignment: 11/03/2021

160 SIN MING DRIVE #06-01

30/03/2021 Inspected At: SIN MING AUTOCITY Date Inspected:

REPAIRER: THIAM HENG HUAT PTE LTD

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

3/14/22, 2:12 PM

Part Source: (Last Synchronised: 12 Mar 2022)

Parts: N/A TOYOTA HIACE 3.0 COMMUTER GL (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PC3806S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	782.00 FL	*594.00 FL
2	1		*FRONT BUMPER TOP BEAM	Not Necessary	362.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER (2 Pcs)	Broken (1 Pc only)	184.00 FL	*92.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	489.00 FL	*320.00 FL
5	1		*FRONT GRILLE	Cut	973.00 FL	*580.00 FL
6	1		*HEADLAMP TOP GARNISH N/S	Not Necessary	282.00 FL	*- FL
7	1		*HEADLAMP N/S	Cracked	1,982.00 FL	*1,168.00 FL
8	1		*HORN ASSY	Not Necessary	198.00 FL	*- FL
9	1		*FOG LAMP N/S	Not Necessary	345.00 FL	*- FL
10	1		*FOG LAMP OUTER GARNISH N/S	Not Necessary	199.00 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	267.00 FL	*- FL
12	1		*FRONT STEP PANEL N/S	Not Necessary	413.00 FL	*- FL
13	1		*FRONT STEP PANEL OUTER N/S	Not Necessary	294.00 FL	*- FL
14	10		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
15	8		*FRONT GRILLE CLIPS	Necessary	44.00 FS	*20.00 FS
16	8		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	44.00 FS	*-FS
17	1		*FRONT LICENCE PLATE & FRAME	Not Necessary	55.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
F=Fra	anchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	7,018.00	2,804.00
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,692.50	688.50	
				Total Parts (S\$)	5,325.50	2,115.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	200.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	30.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	200.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
	Gross Labour Cost (S\$)		2,750.00	430.00
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >