

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA HIACE

Date: 30/03/2021


Engine/Chassis No.:

Claim Type: TP

Date of accident:

VRN: PC3806S

Damaged area: N/S Front



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper	1	\$ 782.00	\$ 782.00
2	Front bumper top beam	1	\$ 362.00	\$ 362.00
3	Front bumper side retainer	2	\$ 92.00	\$ 184.00
4	Front bumper reinforcement	1	\$ 489.00	\$ 489.00
5	Front grille	1	\$ 973.00	\$ 973.00
6	Headlamp top garnish n/s	1	\$ 282.00	\$ 282.00
7	Headlamp n/s	1	\$ 1,982.00	\$ 1,982.00
8	Horn assy	1	\$ 198.00	\$ 198.00
9	Fog lamp n/s	1	\$ 345.00	\$ 345.00
10	Fog lamp outer garnish n/s	1	\$ 199.00	\$ 199.00
11	Front bumper lower grille	1	\$ 267.00	\$ 267.00
12	Front step panel n/s	1	\$ 413.00	\$ 413.00
13	Front step panel outer n/s	1	\$ 294.00	\$ 294.00
Subtotal				\$ 6,770.00
List discount				25.00%
Total				\$ 5,077.50

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips	10	\$ 5.50	\$ 55.00
2	Front grille clips	8	\$ 5.50	\$ 44.00
3	Front bumper lower grille clips	8	\$ 5.50	\$ 44.00
4	Front licence plate & frame	1	\$ 55.00	\$ 55.00
5	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 248.00

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
4	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,750.00
Estimate Grand Total			\$ 8,075.50