Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Jenny Lew Date: 08 Mar 2022

Preliminary Advice

: GBG2535A Insured

Vehicle No

Make

TP Vehicle Accident Date : PC3806S

: 02/03/2021

: 2

No

: TOYOTA HIACE Assignment Date: 11/03/2021

: 30/03/2021 Date of Est. Duration of

Inspection Repair

Inspection At: THIAM HENG HUAT PTE LTD (SIN MING)

176 SIN MING DRIVE, #05-14

SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 8,075.50 **Revised Amount** :S\$ 2,545.50 Check Items (Estimated) :S\$ 0.00 Total :S\$ 2,545.50

Lump Sum Repair :S\$ 2,000.00

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$
Margin for Repair :S\$

Remarks

() The vehicle is repairable at our adjusted amount. We have also co	onfirmed
	excess and policy coverage. Kindly let us have your authorisation	

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.