

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003263/UGA3Q2
Date: 28/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070126975
Claimant Vehicle No :	SMV5892P	Insured Vehicle No :	GBJ8513H
Date of Loss:	10/03/2021	Nature of Claim:	TP
		Claim No:	8385395805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV5892P		
Make & Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Engine No:	R18A12801157
Reg. Date:	21/10/2008 (Man. Year: 2007)	Chassis No:	JHMRN68408S201226
Colour:	Brown	Odometer:	135393 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,558.76	3,523.92	7,034.84	66.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,650.00	2,630.00	61.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,838.76	5,173.92	9,664.84	65.13
Approved Total (Overridden) (S\$)		4,100.00		

Nett Amount (S\$)	14,838.76	4,100.00	10,738.76	72.37
+ Car Rental (6.0 x S\$128.40/day) (S\$)		770.40		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		4,986.85		

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 12/03/2021

Inspected At:

Nineteen Autowerks Pte Ltd (HQ)
 BLK 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE
 Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,270.00 FL	*903.00 FL
2	1		*TAILGATE OUTER GARNISH	Cracked	365.10 FL	*184.00 FL
3	1		*TAILGATE LOGO	Necessary	73.00 FL	*38.00 FL
4	1		*TAILGATE EMBLEM STREAM	Necessary	89.00 FL	*42.00 FL
5	1		*TAILGATE INNER LOCK	Dented / Shorted	258.00 FL	*198.00 FL
6	1		*TAILGATE TRIMBOARD	Deformed / Cracked	466.70 FL	*268.20 FL
7	2		*TAILGATE INNER GARNISH SIDE	Not Necessary	217.00 FL	*- FL
8	1		*TAILGATE INNER GARNISH TOP	Not Necessary	112.60 FL	*- FL
9	1		*TAILGATE WEATHERSTRIP	Twisted	215.00 FL	*166.80 FL
10	2		*TAILGATE HYDRAULIC DAMPER	Not Necessary	255.60 FL	*- FL
11	1		*TAILGATE WINDSCREEN	Shattered	924.00 FL	*924.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	118.00 FL	*86.20 FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	196.40 FL	*- FL
14	1		*REAR WIPER MOTOR	Not Necessary	399.60 FL	*- FL
15	1		*REAR WIPER ARM	Not Necessary	89.40 FL	*- FL
16	1		*REAR WIPER ARM COVER	Not Necessary	72.00 FL	*- FL
17	1		*TAILLAMP	O/S Cracked	851.40 FL	*366.80 FL
18	2		*TAILLAMP LOWER BRACKET	Not Necessary	142.80 FL	*- FL
19	2		*TAILLAMP SEAL	Not Necessary	60.00 FL	*- FL
20	1		*REAR BUMPER	Dented / Deformed	987.00 FL	*665.40 FL
21	2		*REAR BUMPER SIDE RETAINER	Not Necessary	154.40 FL	*- FL
22	2		*REAR BUMPER BRACKET	Not Necessary	108.60 FL	*- FL
23	1		*REAR END PANEL	Repair	848.00 FL	*- FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	207.80 FL	*- FL
25	1		*REAR END PANEL TOP GARNISH COVER	Not Necessary	102.00 FL	*- FL
26	2		*REAR FENDER INNER GARNISH	Not Necessary	724.00 FL	*- FL
27	1		*EXHAUST PIPE ASSY	Not Necessary	970.90 FL	*- FL
28	3		*EXHAUST	Not Necessary	176.40 FL	*- FL
29	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
30	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	50.00 FS	*40.00 FS
31	2		*SET TAILGATE INNER GARNISH SIDE CLIPS	Not Necessary	70.00 FS	*- FS
32	1		*SET TAILGATE INNER GARNISH TOP CLIPS	Not Necessary	35.00 FS	*- FS
33	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	100.00 FS	*- FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*TAILGATE WINDSCREEN TINTED FILM	Necessary	100.00 FS	*100.00 FS
37	1		*TAILGATE SEALANT	Not Necessary	220.00 FS	*- FS
38	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
39	1		*REAR WIPER BLADE	Not Necessary	80.00 FS	*- FS
40	2		*SET TAILLAMP CLIPS	Not Necessary	60.00 FS	*- FS
41	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
42	1		*REVERSE CAMERA	Not Necessary	420.00 FS	*- FS
43	1		*SET REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS
44	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
46	2		*SET REAR FENDER INNER GARNISH CLIPS	Not Necessary	110.00 FS	*- FS
47	1		*EXHAUST CHROME SLEEVE	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,649.70	4,292.40
- List Item Discount on L Items 20.00/20.00% (S\$)	2,090.94	768.48
Total Parts (S\$)	10,558.76	3,523.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING AND STRENGTHEN PARTS ON ACCIDENT AREA	New	1,600.00	580.00
2	CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	New	80.00	30.00
3	R&R INTERIOR UPHOLSTERY	New	200.00	80.00
4	R&R TAILGATE COMPONENT	New	100.00	60.00
5	R&R TAILGATE WINDSCREEN	New	180.00	120.00
6	R&R REVERSE SENSOR AND CHECK	New	100.00	50.00
7	R&R EXHAUST ASSY	New	320.00	0.00
8	TO APPLY UNDERCOATING FOR RUST PROOFING	New	200.00	30.00
9	SPRAY PAINTING ON ACCIDENT AREA	New	1,500.00	700.00
Gross Labour Cost (\$\$)			4,280.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >