

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Neg. No. 13300713010 GST Neg. No. 13 300713010						
Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD		Ref:	CS/SGK21003267/Avf3e2	
	C/O Sedgwick Sing 30 Cecil Street, Le	gapore Pte Ltd vel 12, Prudential Tower		Date:	09/04/2021	
	SINGAPORE 0497	12				
				Code:	INC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	ł	XD 5950U	
	Policy No.	NTUC: PC/0687936	Coverage (\$)		0.00	
	Claim No.	SGK: 6004139	Excess (\$)		0.00	
	Assign From	KENNTH NEO	Assign Date		12/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI FP51JDR4RDEA	c.c		12882	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	FP51JDA00913	Colour		BLUE	
	Odometer	327030 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	295/80 R22.5	GOLDSHIELD		6 mm	
	L/H Front Tyre	295/80 R22.5	GOLDSHIELD		6 mm	
	R/H Rear Tyre	295/80 R22.5	GOLDSHIELD		6 mm	
	L/H Rear Tyre	295/80 R22.5	GOLDSHIELD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/02/2021	Inspection Dat	:e	12/03/2021	
	Survey held at	Survey held at SMARTONE AUTO PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.					
5 h	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair Section 1 Deposit Days of Repair Section 1 Deposit Days Days Section 1 Deposit Days Section 1 Deposit Days Section 2 Days Section 1 Deposit Days Section 1 Deposit Days Section 1 Deposit Days Section 2 Days Section 1 Deposit Days Section 1 Deposit Days Section 2 Days Section 1 Deposit Days Section 2 Days Sectio					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 28 Working Days					