

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

|--|

AXA INSURANCE PTE LTD CS3/ASM21003272/R1vf3e2 Ref:

| AXA INSURANCE | . I IL LID | IV. | CI. | 000/A01012 100021 2/10 101062 |
|-------------------------------|-------------------------|------------------------|------|-------------------------------|
| 8 SHENTON WAY TOWERSINGAPO | - | Di | ate: | 29/03/2021 |
| ATTN : WINNIE H | 0 | C | ode: | ASM |
| | Policy Particul | ars :- (THIRD PARTY | CLAI | M) |
| Insured Veh. | XE 810T | Veh. Inspected | | XE 5930Y |
| Policy No. | GA562430 | Coverage (\$) | | 0.00 |
| Claim No. | S1M034J1 | Excess (\$) | | 0.00 |
| Assign From | WINNIE HO | Assign Date | | 11/03/2021 |
| • | Vehicle F | Particulars & Conditio | n | |
| Make & Model | ISUZU CYH52S | c.c | | 15681 |
| Engine No. | HIDDEN | Year of Reg. | | 2009 |
| Chassis No. | JALCYH52S97000052 | Colour | | MULTI COLOUR |
| Odometer | 339047 KM | Steering | | IN ORDER |
| Brakes | IN ORDER | Modification | | NIL |
| General | FAIR | | | |
| | Co | nditions of Tyres | | |
| | Size | Make | | Balance |
| R/H Front Tyre | 315/80 R22.5 | DELUN | | 8 mm |
| L/H Front Tyre | 315/80 R22.5 | DELUN | | 8 mm |
| R/H Rear Tyre | 315/80 R22.5 (D) | DELUN | | 8/8 mm |
| L/H Rear Tyre | 315/80 R22.5 (D) | DELUN | | 8/8 mm |
| | Desc | ription of Damages | | |
| THE VEHICLE SU | ISTAINED DAMAGES AT THE | FRONT PORTION. | | |
| | Ge | neral Information | | |
| Accident Date | 03/03/2021 | Inspect Date / Tir | ne | 12/03/2021 (05:09 PM) |
| Survey held at | HOCK SAN MOTOR WORK | S PTE LTD | | |

7 SOON LEE STREET #05-08 ISPACE

SINGAPORE 627608

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Report Ref No. CS3/ASM21003272/R1vf3e2

Inspected By

5b.

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser