

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21003274/UPS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000461
Claimant Vehicle No :	SLZ3426G	Insured Vehicle No :	XE1482A
Date of Loss:	11/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001098

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3426G	Engine No:	L15B71672728
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFK4840HT000007
Reg. Date:	27/04/2018 (Man. Year: 2017)	Odometer:	78522 km
Colour:	Grey		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,644.50	5,523.12	15,121.38	73.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	2,020.00	1,730.00	46.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,394.50	7,543.12	16,851.38	69.08
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	24,394.50	6,000.00	18,394.50	75.40
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		6,567.45		
Global Sum Settlement (S\$)		6,560.00		

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 12/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2021)
Parts:	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ3426G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	988.20 F	*982.20 FL
2	2		*FRONT DOOR HINGES O/S	Bent	190.00 F	*164.00 FL
3	1		*FRONT DOOR CHECKER O/S	Twisted	121.00 F	*115.00 FL
4	1		*FRONT DOOR GLASS OUTER MOULDING O/S	Necessary	106.80 F	*86.20 FL
5	1		*FRONT DOOR FRAME OUTER CHROME MOULDING O/S	Cracked	188.90 F	*166.50 FL
6	1		*FRONT DOOR INNER LOCK O/S	Serviceable	366.50 F	*- FL
7	1		*FRONT DOOR INNER RUBBER O/S	Necessary	182.30 F	*182.30 FL
8	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Cracked	866.20 F	*485.20 FL
9	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Shorted	450.50 F	*355.50 FL
10	1		*FRONT DOOR MIRROR ASSY O/S	Cracked	1,088.20 F	*680.20 FL
11	1		*FRONT DOOR OUTER HANDLE O/S	Not Necessary	244.90 F	*- FL
12	1		*FRONT DOOR INNER HANDLE BRACKET O/S	Cracked	211.20 F	*145.30 FL
13	1		*FRONT DOOR OUTER PILLAR O/S	Repair	899.20 F	*- FL
14	1		*ROCKER PANEL GARNISH O/S	Deformed / Torn	998.00 F	*820.00 FL
15	1		*FRONT FENDER O/S	Badly Dented	665.20 F	*451.20 FL
16	1		*FRONT FENDER INNER SHIELD O/S	Deformed	288.60 F	*182.40 FL
17	1		*FRONT SHOCK ABSORNER O/S	Not Necessary	566.20 F	*- FL
18	1		*FRONT LOWER ARM O/S	Bent	545.20 F	*244.50 FL
19	1		*FRONT KNUCKLE ARM O/S	Bent	582.50 F	*258.60 FL
20	1		*FRONT KNUCKLE ARM BEARING O/S	Necessary	250.90 F	*116.30 FL
21	1		*FRONT WHEEL HUB O/S	Bent	228.90 F	*181.00 FL
22	1		*FRONT DRIVE SHAFT O/S	Not Necessary	1,420.20 F	*- FL
23	1		*FRONT CROSS MEMBER	Not Necessary	980.30 F	*- FL
24	1		*FRONT STEERING RACK ASSY	Not Necessary	2,210.20 F	*- FL
25	1		*FRONT BUMPER	Not Necessary	688.20 F	*- FL
26	1		*FRONT BUMPER LAMP O/S	Not Necessary	66.90 F	*- FL
27	1		*HEADLAMP O/S	Not Necessary	1,820.20 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*BONNET	Repair	788.90 F	*- FL
29	1		*FRONT WINDSCREEN MOULDING	Not Necessary	110.20 F	*- FL
30	1		*SET FRONT DOOR VISOR O/S	Necessary	80.00 FS	*50.00 FS
31	1		*FRONT DOOR MIRROR CARBON COVER O/S	Broken	800.00 FS	*250.00 FS
32	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	50.00 FS	*50.00 FS
33	1		*SET ROCKER PANEL GARNISH CLIPS O/S	Necessary	50.00 FS	*40.00 FS
34	1		*SET ROCKER PANEL INNER SHIELD CLIPS O/S	Necessary	50.00 FS	*40.00 FS
35	1		*FRONT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*FRONT SPORT RIM O/S	Bent / Warped	1,200.00 FS	*600.00 FS
37	1		*FRONT TYRE O/S	Not Necessary	200.00 FS	*- FS
38	1		*SET FORNT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	20,644.50	6,646.40
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	1,123.28
Total Parts (S\$)	20,644.50	5,523.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO SPRAY RUST PROOFING	New	120.00	60.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	450.00	120.00
5	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,080.00
Gross Labour Cost (S\$)			3,750.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >