

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21003276/KTD3E2

Date: 30/06/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001622294

Claimant Vehicle No : SMW5733K

Insured Vehicle No : SLN5168B

Date of Loss: 11/03/2021

Nature of Claim: TP

Claim No: 254563

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMW5733K**

Make & Model: TOYOTA SIENTA, 1.5 (A)

Engine No: HIDDEN

Reg. Date: 01/11/2020 (Man. Year: 2020)

Chassis No: MHFZ28H3X00068874

Colour: Metallic Silver

Odometer: 6362 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15

Rear Tyre Size: 185/60R15

Front Left Side: Hankook 9 mm

Rear Left Side: Hankook 9 mm

Front Right Side: Hankook 9 mm

Rear Right Side: Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,614.55	2,816.62	797.93	22.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,190.00	1,030.00	160.00	13.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,804.55	3,846.62	957.93	19.94

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 12/03/2021 Inspected At:

Rc Auto-160 Sin Ming (HQ)
160 SIN MING DRIVE, #06-20 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2021)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW5733K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	398.30 FL	*398.30 FL
2	1		*FRONT BUMPER RETAINER	Distorted	59.70 FL	*59.70 FL
3	1		*FRONT FENDER	Buckled	530.10 FL	*530.10 FL
4	1		*FRONT HEADLAMP	Cut	1,019.30 FL	*1,019.30 FL
5	1		*SPORTS RIM	Dented	1,748.10 FL	*1,748.10 FL
6	1		*FRONT ABSORBER	Serviceable	375.80 FL	*- FL
7	1		*FRONT LOWER ARM	Serviceable	688.10 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,819.40	3,755.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,204.85	938.88
Total Parts (\$\$)	3,614.55	2,816.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	60.00	60.00
2	TO RENEW ABOVE PARTS	New	500.00	400.00
3	TO CHECK WIRING	New	30.00	20.00
4	TO RESPRAY JOB	New	600.00	550.00
Gross Labour Cost (\$\$)			1,190.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >