

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21003279/T1QF3E2

**Date:** 08/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800037379  
**Claimant Vehicle No :** GBE4376P **Insured Vehicle No :** SLZ687P  
Date of Loss: 17/12/2020 Nature of Claim: TP Claim No: 4873264005SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE4376P**  
Make & Model: NISSAN NV200, 1.5 (M) Engine No: K9KC400D055008  
Reg. Date: 10/12/2015 (Man. Year: 2015) Chassis No: VSKYBAM20Z0117334  
Colour: Grey Odometer: 154374 km  
Engine Capacity: 1461 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 12/03/2021  
Date Inspected: 12/03/2021 Inspected At: Hsl Auto Service (HQ)  
1 KAKI BUKIT AVENUE 6, #01-02, AUTOBAY @  
KAKI BUKIT,  
SINGAPORE 417883  
Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
5	1		*REAR RH FENDER	Repair	0.00 F	*- F
6	1		*REAR RH DOOR	Repair	0.00 F	*- F
7	1		*REAR RH DOOR LOWER HINGE	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >