

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003292/DPA3Q2
Date: 29/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070102635
Claimant Vehicle No :	GBE5875J	Insured Vehicle No :	SMT6970B
Date of Loss:	12/03/2021	Nature of Claim:	TP
		Claim No:	4290306995SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5875J	Engine No:	YD25387616A
Make & Model:	NISSAN NV350, 2.5 5AT 5DR EURO V (A)	Chassis No:	JN1MC2E26Z0005785
Reg. Date:	27/01/2016 (Man. Year: 2015)	Odometer:	85070 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,190.10	2,947.08	20,243.02	87.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	1,560.00	4,210.00	72.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,960.10	4,507.08	24,453.02	84.44
Approved Total (Overridden) (S\$)		3,600.00		

(S\$)	28,960.10	3,600.00	25,360.10	87.57
+ GST 7.00/7.00% (S\$)	2,027.21	252.00	1,775.21	87.57
Nett Amount (S\$)	30,987.31	3,852.00	27,135.31	87.57
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		4,388.45		
Global Sum Settlement (S\$)		4,350.00		

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
 Singapore 568047

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,240.20 FL	*- FL
2	1		*BONNET SIDE PANEL LH	Not Necessary	498.70 FL	*- FL
3	1		*HEAD LAMP LH	Mtg Cracked	1,892.40 FL	*401.70 FL
4	1		*HEAD LAMP PANEL LH	Not Necessary	398.50 FL	*- FL
5	1		*FRONT GRILLE	Not Necessary	394.60 FL	*- FL
6	1		*FRONT GRILLE BASE	Not Necessary	422.30 FL	*- FL
7	1		*FRONT GRILLE LOGO	Not Necessary	92.40 FL	*- FL
8	1		*FRONT BUMPER	Distorted / Cut	701.00 FL	*571.90 FL
9	1		*FRONT BUMPER SIDE RETAINER LH/RH	O/S Not Necessary / N/SCracked	170.00 FL	*75.00 FL
10	1		*FRONT BUMPER FOG LAMP LH	Not Necessary	320.90 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	289.90 FL	*- FL
12	1		*FRONT BUMPER FOG LAMP HOLDER LH	Not Necessary	284.50 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	1,430.00 FL	*- FL
14	1		*FRONT BUMPER GRILLE	Not Necessary	490.00 FL	*- FL
15	1		*FRONT REINFORCEMENT BAR LOWER	Not Necessary	1,092.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Not Necessary	1,680.00 FL	*- FL
17	1		*FRONT INTER -COOLER ASSY	Not Necessary	1,816.00 FL	*- FL
18	1		*FRONT STEP GARNISH LH	Cut	298.40 FL	*298.40 FL
19	1		*FRONT DOOR LH	Dented	1,490.20 FL	*1,071.90 FL
20	1		*FRONT DOOR WINDOW MOULDING LH	Not Necessary	310.20 FL	*- FL
21	2		*FRONT DOOR HINGE	Not Necessary	299.60 FL	*- FL
22	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	980.80 FL	*- FL
23	1		*FRONT DOOR WEATHER STRIP LH	Serviceable	311.90 FL	*- FL
24	1		*FRONT RIM LH	Not Necessary	687.40 FL	*- FL
25	1		*FRONT RIM COVER LH	Not Necessary	198.20 FL	*- FL
26	1		*FRONT WHEEL BEARING & HUB ASSY LH	Not Necessary	410.90 FL	*- FL
27	1		*FRONT KNUCKLE ARM LH	Not Necessary	898.70 FL	*- FL
28	1		*FRONT LOWER ARM LH	Not Necessary	501.90 FL	*- FL
29	1		*FRONT ABSORBER LH	Not Necessary	489.80 FL	*- FL
30	1		*FRONT STABILIZER LINK LH	Not Necessary	298.70 FL	*- FL
31	1		*STEERING RACK & PINION ASSY	Not Necessary	2,498.90 FL	*- FL
32	1		*OIL COOLER	Bent / Dented	1,600.00 FL	*672.30 FL
33	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
35	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*DOOR COMPANY STICKER	Necessary	400.00 FS	*25.00 FS
38	1		*DOOR ADVERTISEMENT STICKER	Necessary	500.00 FS	*120.00 FS
39	1		*FRONT DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,639.00	3,256.20
- List Item Discount on L Items 10.00/10.00% (\$)	2,448.90	309.12
Total Parts (\$)	23,190.10	2,947.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	750.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	600.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
4	TO RNR OIL COOLER TO FACILITATE REPAIRS	New	200.00	80.00
5	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	New	250.00	60.00
6	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			5,770.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >