

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: AIG ASIA PACIFIC INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMT6970B [YOUR INSURED] & GBE5875J [OUR CLIENT]
ON 12/03/2021.

ESTIMATED REPAIR COSTS FOR GBE5875J

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET HH	\$ 1,240.20	X
1PC	BONNET SIDE PANEL LH HH	\$ 498.70	X
1PC	HEAD LAMP LH <i>crack mounting</i> 401.70	\$ 1,892.40	✓
1PC	HEAD LAMP PANEL LH HH	\$ 398.50	X
1PC	FRONT GRILLE HH	\$ 394.60	X
1PC	FRONT GRILLE BASE HH	\$ 422.30	X
1PC	FRONT GRILLE LOGO HH	\$ 92.40	X 571.90
1PC	FRONT BUMPER <i>distorted / cut.</i> 0/3 HH	\$ 701.00	✓
1PC	FRONT BUMPER SIDE RETAINER LH / RH @ \$85.00 EACH <i>cut H/S cut</i>	\$ 170.00	X ✓
1PC	FRONT BUMPER FOG LAMP LH HH 75.00	\$ 320.90	X
1PC	FRONT BUMPER FOG LAMP GARNISH LH HH	\$ 289.90	X
1PC	FRONT BUMPER FOG LAMP HOLDER LH HH	\$ 284.50	X
1PC	FRONT BUMPER FOG LAMP WIRE HARNESS HH	\$ 1,430.00	X
1PC	FRONT BUMPER GRILLE HH	\$ 490.00	X
1PC	FRONT REINFORCEMENT BAR LOWER HH	\$ 1,092.00	X
1PC	FRONT SUPPORT PANEL HH	\$ 1,680.00	X
1PC	FRONT INTER-COOLER ASSY HH	\$ 1,816.00	X
1PC	FRONT STEP GARNISH LH <i>cut.</i>	\$ 298.40	✓
1PC	FRONT DOOR LH <i>dent</i> 1071.90	\$ 1,490.20	✓
1PC	FRONT DOOR WINDOW MOULDING LH HH	\$ 310.20	X
2PCS	FRONT DOOR HINGE @ \$149.80 EACH HH	\$ 299.60	X
1PC	FRONT DOOR INNER TRIM BOARD LH HH	\$ 980.80	X
1PC	FRONT DOOR WEATHER STRIP LH <i>cut 3Vc</i>	\$ 311.90	X
1PC	FRONT RIM LH HH	\$ 687.40	X
1PC	FRONT RIM COVER LH HH	\$ 198.20	X
1PC	FRONT WHEEL BEARING & HUB ASSY LH HH	\$ 410.90	X
1PC	FRONT KNUCKLE ARM LH HH	\$ 898.70	X
1PC	FRONT LOWER ARM LH HH	\$ 501.90	X
1PC	FRONT ABSORBER LH HH	\$ 489.80	X
1PC	FRONT STABILIZER LINK LH HH	\$ 298.70	X

1PC	STEERING RACK & PINION ASSY HH	\$ 2,498.90	X
1PC	OIL COOLER 1st/2nd	672.30	1.600.00 ✓

3091.20

2782.08

PARTS SUM: \$ 22,889.00
 PARTS LESS 10%: \$ 2,288.90
 PARTS TOTAL: \$ 20,600.10

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY HEAD LAMP CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS HH	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS HH	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY DOOR COMPANY STICKER HH	\$ 400.00	25/-
*	TO SUPPLY DOOR ADVERTISEMENT STICKER HH	\$ 500.00	120/-
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS HH	\$ 50.00	X
		165.00	
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00	750/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00	600/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
	OIL COOLER		
*	TO RNR INTER-COOLER TO FACILITATE REPAIRS	\$ 200.00	80/-
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 250.00	60/-
*	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00	HH
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	\$ 120.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
		1560/-	
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	HH

LABOUR & S/N TOTAL: \$ 6,920.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 27,520.10

15/03/2021 @ 1100hrs

Not Antwnl

4507.08

4/5 3600/-

2/5mm

4 days.

R
Jm

2KK Auto

Check part prices.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: