

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21003293/DVD3E2

Date: 29/10/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29144152AT2
Claimant Vehicle No :	FBN5299A	Insured Vehicle No :	SJA68G
Date of Loss:	25/01/2021	Nature of Claim:	TP
		Claim No:	633344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN5299A	Engine No:	KC27E2208694
Make & Model:	HONDA FS150F, 149cc	Chassis No:	PMKKC2760KB205276
Reg. Date:	26/10/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Black		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90 R17	Rear Tyre Size:	110/70 R17
Front Left Side:	Pirelli 2 mm	Rear Left Side:	Pirelli 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,870.50	3,522.50	1,348.00	27.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	330.00	380.00	53.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,580.50	3,852.50	1,728.00	30.96
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	5,580.50	2,800.00	2,780.50	49.83

INSPECTION

Date of Assignment:	12/03/2021	Sg 98 Motor Pte Ltd (HQ)
Date Inspected:	15/03/2021 Inspected At:	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
		#01-21
		Singapore 569622
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2021)	
Parts:	N/A	HONDA FS150F 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN5299A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Distorted	150.00 FL	*150.00 FL
2	1		*BRAKE LEVER	Cut	90.00 FL	*90.00 FL
3	1		*CENTRE HEAD PANEL	Cut	160.00 FL	*160.00 FL
4	1		*SET STEERING CONE BEARING	Damaged	120.00 FL	*120.00 FL
5	1		*SET FORK TUBE	Damaged	480.00 FL	*480.00 FL
6	1		*FORK UNDER BRACKET	Damaged	240.00 FL	*240.00 FL
7	1		*FRONT MUDGUARD	Broken	180.00 FL	*180.00 FL
8	2		*SIDE PANEL L/RH	Broken	180.00 FL	*180.00 FL
9	1		*SET RIM	Repair	325.00 FL	*- FL
10	1		*WHEEL AXLE	Distorted	120.00 FL	*120.00 FL
11	1		*BRAKE DISC	Not Necessary	260.00 FL	*- FL
12	1		*BRAKE CALIPER	Damaged	180.00 FL	*180.00 FL
13	1		*BRAKE HOSE / CABLE	Broken	150.00 FL	*150.00 FL
14	1		*FRONT SIGNAL RH	Cut	80.00 FL	*80.00 FL
15	1		*INNER PANEL GARNISH	Cracked	190.00 FL	*190.00 FL
16	1		*SET ENGINE GUARD	Broken	220.00 FL	*220.00 FL
17	1		*HEAD LAMP TOP COVER	Not Necessary	250.00 FL	*- FL
18	1		*FORK OIL SEAL	Necessary	70.00 FL	*70.00 FL
19	1		*FORK OIL	Necessary	60.00 FL	*20.00 FL
20	1		*RADIATOR ASSY	Bent / Punctured	350.00 FL	*350.00 FL
21	1		*RADIATOR FAN MOTOR ASSY	Not Necessary	280.00 FL	*- FL
22	1		*EXHAUST PIPE	Bent / Dented	480.00 FL	*480.00 FL
23	1		*SET MIRROR (N/S NOT NECESSARY)	O/S Dislodged / Missing	110.00 FL	*55.00 FL
24	1		*HAND REST	O/S Damaged /N/S Not Necessary	120.00 FL	*60.00 FL
25	1		*BRAKE PUMP ASSEMBLY	Broken / Dislodged	250.00 FL	*250.00 FL
26	1		*NUMBER PLATE	Not Necessary	15.00 FS	*- FS
27	1		*FOG LIGHT	Not Necessary	120.00 FS	*- FS
28	1		*BODY STICKER	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,380.00	3,905.00
- List Item Discount on L Items 10.00/10.00% (\$)	509.50	382.50
Total Parts (\$)	4,870.50	3,522.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	0.00
2	REMOVE & REPLACE PARTS, ALIGN & ETC	New	250.00	150.00
3	REMOVE & REPLACE FORK ASSY, RIM, CALIPER, DISC	New	200.00	100.00
4	ALIGN BODY FRAME	New	200.00	80.00
Gross Labour Cost (\$\$)			710.00	330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >