

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003294/KPS3Q2**Date:** 12/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210002614
Claimant Vehicle No :	SMP2460D	Insured Vehicle No :	GBF6472B
Date of Loss:	10/03/2021	Nature of Claim:	TP
		Claim No:	4922071047SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2460D	Engine No:	HR16913478C
Make & Model:	NISSAN SYLPHY, 1.6 (A)	Chassis No:	MNTBBAB17Z0030361
Reg. Date:	25/09/2017 (Man. Year: 2017)	Odometer:	30609 km
Colour:	Metallic Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,584.92	666.18	918.74	57.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	380.00	680.00	64.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,644.92	1,046.18	1,598.74	60.45
+ GST 7.00/7.00% (S\$)	185.14	73.23	111.91	60.45
Nett Amount (S\$)	2,830.06	1,119.41	1,710.65	60.45
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,241.41		
Global Sum Settlement (S\$)		1,200.00		

INSPECTION

Date of Assignment:	12/03/2021	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Date Inspected:	22/03/2021 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LOCK	Repair	115.00 FL	*- FL
2	1		*REAR BOOT LOCK SENSOR	Serviceable	95.00 FL	*- FL
3	1		*REAR BOOR RUBBER	Serviceable	112.00 FL	*- FL
4	1		*REAR BUMPER	Mtg Cracked	679.00 FL	*679.00 FL
5	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	84.00 FL	*- FL
6	12		*REAR BUMPER CLIPS	Necessary	61.20 FL	*61.20 FL
7	1		*REAR BUMPER SPONGE CTR	Serviceable	55.00 FL	*- FL
8	2		*REAR BUMPER SPONGE LH & RH	Serviceable	201.60 FL	*- FL
9	2		*REAR BUMPER STAY LH & RH	Repair	136.00 FL	*- FL
10	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					1,738.80	740.20
- List Item Discount on L Items 10.00/10.00% (\$\$)					153.88	74.02
Total Parts (\$\$)					1,584.92	666.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	60.00
2	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD ,TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	500.00	120.00
3	TO SPRAY REAR BUMPER ,REAR END PANEL	New	500.00	200.00
Gross Labour Cost (\$\$)			1,060.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >