

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003299/AEA3Q2
Date: 17/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700008134-04
Claimant Vehicle No :	SGK165S	Insured Vehicle No :	SFF72P
Date of Loss:	11/03/2021	Nature of Claim:	TP
		Claim No:	3316256807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK165S		
Make & Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Engine No:	27091031637997
Reg. Date:	14/06/2018 (Man. Year: 2018)	Chassis No:	WDC1569422J511435
Colour:	Silver	Odometer:	61042 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,161.34	269.30	4,892.04	94.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	710.00	1,510.00	68.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,381.34	979.30	6,402.04	86.73
+ GST 7.00/7.00% (S\$)	516.69	68.55	448.14	86.73

Nett Amount (S\$)	7,898.03	1,047.85	6,850.18	86.73
		+ Loss of Use (4.0 x S\$60.00/day) (S\$)	240.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	1,295.30	

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 15/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,645.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	80.00 FL	*- FL
3	1		*FRONT HEADLAMP	Not Necessary	2,855.30 FL	*- FL
4	1		*FRONT FENDER RH	Repair	855.30 FL	*- FL
5	1		*FRONT FENDER PROTECTOR RH	Cut	277.00 FL	*277.00 FL
6	1		*FRONT FENDER PROTECTOR	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,732.60	297.00
- List Item Discount on L Items 10.00/10.00% (\$)	571.26	27.70
Total Parts (\$)	5,161.34	269.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,000.00	200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	WIRING CHECK	New	120.00	60.00
4	TO REMOVE AND REFIX FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,220.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >