

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21003300/T1QF3E2

Date: 28/04/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT002120		
Claimant Vehicle No :	SHD3446L	Insured Vehicle No :	SKB2620G		
Date of Loss:	11/03/2021	Nature of Claim:	TP	Claim No:	M2101210

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3446L	Engine No:	D4DFDU561526
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU093256
Reg. Date:	28/07/2016 (Man. Year: 2016)	Odometer:	728107 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,899.44	253.76	2,645.68	91.25
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,650.00	1,170.00	480.00	29.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,560.44	1,434.76	3,125.68	68.54
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	4,560.44	1,150.00	3,410.44	74.78
+ GST 7.00/7.00% (S\$)	319.23	80.50	238.73	74.78
Nett Amount (S\$)	4,879.67	1,230.50	3,649.17	74.78

INSPECTION

Date of Assignment:	12/03/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/03/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3446L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER COVER	Repair	1,106.00 FL	-	*- FL
2	1		*REAR DOOR COMFORT APP	Cut	80.00 FS	-	*80.00 FS
3	1		*REAR DOOR PANEL LH	Repair	2,201.10 FL	-	*- FL
4	1		*REAR WHEEL CAP	Cut	217.20 FL	-	*217.20 FL
					Sub Total (S\$)	3,604.30	297.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	704.86	43.44
					Total Parts (S\$)	2,899.44	253.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	420.00
2	SPRAY PAINTING	New	800.00	750.00
3	TUFF COATING	New	60.00	0.00
4	REMOVE/REFIX REAR DOOR PART.	New	90.00	0.00
Gross Labour Cost (\$\$)			1,650.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >