

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003303/ARS3Q2
Date: 20/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070130859
Claimant Vehicle No :	SMU8857C	Insured Vehicle No :	SJY6878U
Date of Loss:	09/03/2021	Nature of Claim:	TP
		Claim No:	1485782242SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8857C	Engine No:	PE10284717
Make & Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Chassis No:	JM6CW1071G0122943
Reg. Date:	31/12/2015 (Man. Year: 2015)	Odometer:	73703 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,292.80	3,010.16	1,282.64	29.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,000.00	800.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,092.80	4,010.16	2,082.64	34.18
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	6,092.80	3,200.00	2,892.80	47.48
+ GST 7.00/7.00% (S\$)	426.50	224.00	202.50	47.48
Nett Amount (S\$)	6,519.30	3,424.00	3,095.30	47.48
+ Car Rental (6.0 x S\$180.00/day) (S\$)		1,080.00		
Nett Liability (S\$)		4,504.00		

INSPECTION

Date of Assignment: 11/03/2021

Date Inspected: 11/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

J-mart Motor Pte Ltd (HQ)
Blk 5 Defu Lane 10, #01-578
Singapore 539186

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,771.10 FL	*1,637.00 FL
2	1		*LOGO EMBLEM	Necessary	99.00 FL	*99.00 FL
3	1		*MAZDA EMBLEM	Necessary	60.20 FL	*60.20 FL
4	1		*5 EMBLEM	Necessary	84.40 FL	*84.40 FL
5	1		*SKYACTIV EMBLEM	Necessary	110.60 FL	*110.60 FL
6	1		*TAILGATE LOCK	Not Necessary	233.00 FL	*- FL
7	1		*TAILGATE W/STRIP	Not Necessary	259.60 FL	*- FL
8	1		*REAR BUMPER	Deformed	1,050.00 FL	*961.00 FL
9	2		*REAR BUMPER RETAINER	Necessary	164.00 FL	*164.00 FL
10	8		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	463.10 FL	*294.00 FL
12	1		*END PANEL	Repair	656.00 FL	*- FL
13	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
14	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,291.00	3,700.20
- List Item Discount on L Items 20.00/20.00% (\$)	998.20	690.04
Total Parts (\$)	4,292.80	3,010.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	TRANSFER TAILGATE FITTING	New	80.00	80.00
4	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			1,800.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >