

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003322/GVD3E2

Date: 20/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070112853		
Claimant Vehicle No :	JQP4601	Insured Vehicle No :	SJJ1651T		
Date of Loss:	30/01/2021	Nature of Claim:	TP	Claim No:	7673994863SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JQP4601	Engine No:	0399E269284
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	PMYUG0410E0269284
Reg. Date:	06/01/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	70/90-17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	15/03/2021		
Date Inspected:	15/03/2021	Inspected At:	Freesion Autodrive (Kaki Bukit) 25 Kaki Bukit Rd 4, Synergy @KB #03-33 Singapore 417800
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Necessary	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
3	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*HANDLE BAR GRIP	Necessary	0.00 F	*- F
6	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
7	1		*SIDE FAIRING LH	Cut	0.00 F	*- F
8	1		*REAR FAIRING LH	Cut	0.00 F	*- F
9	1		*FRONT FOOT REST LH	Bent	0.00 F	*- F
10	1		*FOOT GEAR SHIFTER	Distorted	0.00 F	*- F
11	1		*REAR TYRE RIM SPOKE	Cut	0.00 F	*- F
12	1		*SWING ARM LH	Dented	0.00 F	*- F
13	1		*STICKER	Necessary	0.00 F	*- F
14	1		*PILLION HAND GRIP	Cut	0.00 F	*- F
15	1		*LH TAILBOARD	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >