

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21003323/UGS3Q2
Date: 14/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0007747
Claimant Vehicle No :	SKE1534M	Insured Vehicle No :	SMH1316L
Date of Loss:	12/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001080

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE1534M	Engine No:	1ZRX164796
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REE104128626
Reg. Date:	10/02/2012 (Man. Year: 2012)	Odometer:	123946 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,412.40	927.65	4,484.75	82.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,080.00	1,430.00	56.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,922.40	2,007.65	5,914.75	74.66
Approved Total (Overridden) (S\$)		1,600.00		

Nett Amount (S\$)	7,922.40	1,600.00	6,322.40	79.80
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,757.45		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2021)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE1534M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	855.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Not Necessary	48.00 F	*- FL
3	1		*BOOTLID 1.6 EMBLEM	Not Necessary	42.00 F	*- FL
4	1		*BOOTLID COROLLA EMBLEM	Not Necessary	45.00 F	*- FL
5	1		*BOOTLID ALTIS EMBLEM	Not Necessary	43.00 F	*- FL
6	1		*BOOTLID VVTI EMBLEM	Not Necessary	42.00 F	*- FL
7	1		*REAR BUMPER	Dented / Deformed	685.10 F	*588.20 FL
8	1		*REAR BUMPER BRACKETS	O/S Bent	133.00 F	*66.50 FL
9	1		*REAR BUMPER REFLECTOR O/S	Cracked	65.20 F	*65.20 FL
10	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	130.20 F	*65.10 FL
11	1		*REAR BUMPER SPONGE	Torn	299.20 F	*135.20 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
13	2		*TAILLAMPS	Not Necessary	680.20 F	*- FL
14	2		*TAILLAMP HOUSING PANELS	Not Necessary	816.20 F	*- FL
15	2		*TAILLAMP LOWER APRON PANELS	Not Necessary	230.00 F	*- FL
16	1		*REAR END PANEL	Repair	580.10 F	*- FL
17	1		*REAR END PANEL GARNISH	Not Necessary	288.10 F	*- FL
18	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
19	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
20	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,412.40	1,170.20
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	242.55
Total Parts (\$\$)	5,412.40	927.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	0.00
5	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,000.00	400.00
7	TO PUTTY & SPRAY PAINTING	New	1,000.00	600.00
			Gross Labour Cost (S\$)	2,510.00
				1,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >