

PERFECT AUTOMOBILE APPRAISAL SERVICES

10 Hougang Street 11 #14-29 The Minton Singapore 534080

Hand phone No. 96683949 Fax No. 63880908

Company Registration No. 53103119E

THIRD PARTY CLAIM

To : Foo Sey Hiang
c/o : TSL Auto Garage
Block 4 Joo Chiat Road
#12-1171 Joo Chiat Complex
Singapore 420004

Date : 15th December 2020

Our Ref : PA/MI/20/1029/1

REFERENCE :

ASSIGNED BY : Owner
ASSIGNED ON : 25th November 2020

SURVEY HELD AT : 68 Kaki Bukit Avenue 6
#02-05 Ark @ Kaki Bukit
Singapore 417896

ACCIDENT DATE : 23rd November 2020
SURVEY DATE : 25th November 2020

VEHICLE DETAILS :

REGN PLATE	: SMF 1246 R	COLOUR	: Black
MAKE & MODEL	: Lexus IS250	GEN BODY WORK	: Good
YEAR REGN	: 2015	AUDIO PLAYER	: Yes
ENG CAPACITY	: 2500cc	AIR CONDITIONER	: Yes
ENGINE NO.	: 4GR1038711	STEERING	: Serviceable
CHASSIS NO	: JTHBF5D2905068119	HAND BRAKE	: Serviceable
MILEAGE	: 66491Km	FOOT BRAKE	: Serviceable

TYRES SIZE & CONDITION :

FRONT O/S : Pirelli 225/45 R 17 approximately 90%
FRONT N/S : Pirelli 225/45 R 17 approximately 90%
REAR O/S : Pirelli 225/45 R 17 approximately 90%
REAR N/S : Pirelli 225/45 R 17 approximately 90%

Note : The above percentage represent the remaining estimated life of the tyre treads.

Our Ref: PA/MI/20/1029/1

Veh. No. : SMF 1246 R

GENERAL DESCRIPTION OF DAMAGES :

At the time of inspection, we noted that this vehicle sustained damages at the rear portion.

For more details of the damages, please see schedule and photographs attached.

Attached seventy-two (72) photographs taken during our inspections.

CONCLUSIONS & RECOMMENDATIONS :

ORIGINAL QUOTATION : \$ 26,694.64

REVISED QUOTATION : \$ 18,800.00 (Lump Sum)

We have thoroughly inspected each and every item on the estimate against the physical damages found on the vehicle. We have listed the breakdown of our findings and our recommendations as per assessment attached.

In normal circumstances, the repairs would take approximately seven (7) days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** repair to the vehicle and the survey was conducted strictly on a '**WITHOUT PREJUDICE**' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

The information contained in these documents is privileged and confidential and is for the exclusive use of the addressee's designation. If you are not the addressee, any enclosure, reproduction, distributions or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for its return.

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s TSL Auto Garage
Block 4 Joo Chiat Road
#12-1171 Joo Chiat Complex
Singapore 420004

Our Ref : PA/MI/20/1029/1

Veh. No. : SMF 1246 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LIST PARTS

1 pc	Boot lid /	dented	\$ 892.10	\$ 892.10 /
1 pc	Boot lid logo /	necessary	\$ 173.70	\$ 173.70 90
1 pc	Boot lid 'Lexus' emblem /	necessary	\$ 110.22	\$ 110.22 80
1 pc	Boot lid 'IS250' emblem /	necessary	\$ 110.22	\$ 110.22 70
1 pc	Boot lid o/s lamp /	cracked	\$ 455.20	\$ 455.20 320
1 pc	Boot lid n/s lamp /	cracked	\$ 455.20	\$ 455.20 320
2 pcs	Rear licence plate lamp @\$102.50	serviceable	\$ 205.00	\$ -
1 pc	Boot lid opening switch X SVC ✓	dented/ failed	\$ 281.65	\$ 281.65 ✓
1 pc	Boot lid inner trim X SVC ✓	torn	\$ 567.93	\$ 567.93 ✓
10 pcs	Boot lid inner trim clip @\$5.50 /	necessary	\$ 55.00	\$ 55.00 473.7
1 pc	Boot lid inner lock /	bent	\$ 1,229.75	\$ 1,229.75 228.4
1 pc	Boot lid lock striker /	bent	\$ 110.65	\$ 110.65 /
1 pc	Boot lid weatherstrip /	torn	\$ 311.43	\$ 311.43 190
2 pcs	Boot lid hinge @\$190.10 X SVC	bent	\$ 380.20	\$ 380.20 X
2 pcs	Boot lid hinge cover @\$89.95 X SVC	distorted	\$ 179.90	\$ 179.90 X
4 pcs	Boot lid stopper @\$10.50 X SVC	serviceable	\$ 42.00	\$ -
1 pc	Rear bumper /	deformed	\$ 936.60	\$ 936.60 /
1 pc	Rear bumper diffuser /	deformed	\$ 489.50	\$ 489.50 /
1 pc	Rear bumper tow cover X SVC	dented	\$ 42.25	\$ 42.25 X
2 pcs	Rear bumper reflector @\$89.95 X SVC	cracked	\$ 179.90	\$ 179.90 X
2 pcs	Rear bumper pdc sensor @\$414.73 /	dented/ failed	\$ 1,658.92	\$ 1,658.92 472.3
1 set	Rear bumper pdc sensor wire harness X SVC	snapped	\$ 411.50	\$ 411.50 X
1 pc	Rear bumper sponge /	cracked	\$ 230.11	\$ 230.11 190
1 pc	Rear bumper reinforcement /	bent	\$ 657.90	\$ 657.90 580
2 pcs	Rear bumper side retainer @\$110.25 /	bent	\$ 220.50	\$ 220.50 165
1 pc	Rear end panel /	dented	\$ 891.90	\$ 891.90 830
1 pc	Rear end panel garnish /	cracked	\$ 395.66	\$ 395.66 /
1 pc	Rear n/s exhaust silencer X Repair	bent	\$ 1,265.90	\$ 1,265.90 X
1 pc	Rear o/s exhaust silencer	repairable	\$ 1,362.50	\$ -
2 pcs	Rear exhaust chrome pipe @\$361.50 /	dented	\$ 723.00	\$ 723.00 460
6 pcs	Rear exhaust mounting @\$48.00 X SVC	snapped	\$ 288.00	\$ 288.00 X
list parts c/f			\$ 15,314.29	\$ 13,704.79

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s TSL Auto Garage
Block 4 Joo Chiat Road
#12-1171 Joo Chiat Complex
Singapore 420004

Our Ref : PA/MI/20/1029/1

Veh. No. : SMF 1246 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

list parts b/f

\$ 15,314.29 \$ 13,704.79

1 pc	Rear o/s exhaust insulator	repairable	\$ 120.60	\$ -
1 pc	Rear n/s exhaust insulator <i>X SVC</i>	dented	\$ 120.60	\$ 120.60 <i>X</i>
1 pc	Rear floor board <i>/</i>	dented	\$ 580.60	\$ 580.60 <i>422</i>
1 pc	Rear floor panel	repairable	\$ 861.90	\$ -
1 pc	Rear floor panel under cover <i>/</i>	torn	\$ 310.60	\$ 310.60 <i>/</i>
1 pc	Rear n/s fender	repairable	\$ 1,560.60	\$ -
2 pcs	Rear fender inner trim @\$531.20 <i>LH- TN PH X SVC</i>	torn	\$ 1,062.40	\$ 1,062.40 <i>412</i>
10 pcs	Rear fender inner trim clip @\$5.50 <i>LH- MC RH X NN</i>	necessary	\$ 55.00	\$ 55.00 <i>27.50</i>
1 pc	Spare tyre retainer lock <i>X SVC</i>	bent	\$ 110.25	\$ 110.25 <i>X</i>
1 pc	Rear tool board <i>/</i>	cracked	\$ 189.90	\$ 189.90 <i>/</i>
1 pc	Rear smart keyless antenna <i>/</i>	cracked	\$ 241.30	\$ 241.30 <i>/</i>
2 pcs	Taillamp @\$637.80 <i>/</i>	cracked	\$ 1,275.60	\$ 1,275.60 <i>70</i>
2 pcs	Taillamp side cover @\$86.60	serviceable	\$ 173.20	\$ -
2 pcs	Taillamp panel @\$241.50 <i>X SVC</i>	dented	\$ 483.00	\$ 483.00 <i>X</i>
1 pc	Rear windscreen moulding	serviceable	\$ 160.54	\$ -
1 pc	Rear licence plate garnish <i>/</i>	cracked	\$ 248.83	\$ 248.83 <i>/</i>
1 pc	Boot lid outer key cylinder lock <i>X SVC</i>	dented	\$ 691.50	\$ 691.50 <i>X</i>
			\$ 23,560.71	\$ 19,074.37 <i>10609.78</i>
Less 10%			\$ 2,356.07	\$ 1,907.44
			\$ 21,204.64	\$ 17,166.93 <i>8930.74</i>

9548.8

S/NETT PARTS

1 set	Rear bumper clip <i>/</i>	necessary	\$ 45.00	\$ 35.00 <i>/</i>
1 set	Rear licence plate with holder <i>/</i>	dented	\$ 65.00	\$ 50.00 <i>/</i>
1 pc	Reverse camera <i>X SVC</i>	dented/ failed	\$ 650.00	\$ 500.00 <i>X</i>
1 set	Rear windscreen sealant <i>X SVC</i>	not necessary	\$ 80.00	\$ -
2 sets	Taillamp clip @\$60.00 <i>/</i>	necessary	\$ 120.00	\$ 100.00 <i>25</i>
			\$ 960.00	\$ 685.00 <i>110</i>

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s TSL Auto Garage
Block 4 Joo Chiat Road
#12-1171 Joo Chiat Complex
Singapore 420004

Our Ref : PA/MI/20/1029/1

Veh. No. : SMF 1246 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

Towing charges.

\$ 120.00 \$ -

To disconnect and check rear electrical wiring, harness, wire sockets, etc.
To remove and reinstall damaged parts, test and rectify for proper functioning.

\$ 80.00 \$ ~~40.00~~ 30

To remove and refix inner trims, garnishes, linings and upholstery to facilitate repairs.

\$ 150.00 \$ ~~100.00~~ 60

To remove and replace rear bumper sensor and reverse camera.

\$ 120.00 \$ 50.00 /

To remove and replace rear exhaust pipe system to facilitate repairs.

\$ 200.00 \$ ~~100.00~~ 60

To remove and refix rear windscreen glass to facilitate repairs and perform water test.

\$ 180.00 \$ -

To remove and replace rear damaged parts as listed above including reinstatement of the necessary attachments and fittings to facilitate repairs. Jack up, straighten, panel beat and reshape the affected parts and components. To correct and realign the necessary parts.

\$ 2,000.00 \$ ~~1,500.00~~ 1000

PERFECT AUTOMOBILE APPRAISAL SERVICES

W/s TSL Auto Garage
Block 4 Joo Chiat Road
#12-1171 Joo Chiat Complex
Singapore 420004

Our Ref : PA/MI/20/1029/1

Veh. No. : SMF 1246 R

QTY	DESCRIPTIONS	COMMENTS/ CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
-----	--------------	------------------------	-----------------------	----------------------

LABOUR CHARGES

To apply rustproofing, reseal tuff-coating treatment to rear replaced/ repaired parts and panels.


\$ 180.00 \$ ~~120.00~~ 60

To putty and spray painting on rear damaged portion including touch up paint on accident affected areas.

\$ 1,500.00 \$ ~~1,200.00~~ 1000
\$ 26,694.64 \$ 20,961.93

2260

The repairer has agreed to undertake repairs on a contractual basis at **Lump Sum \$ 18,800.00** corresponding to supply of parts, labour and spray painting charges.


CHUAH POH SIONG GARY
CAE, MIMI, AMSOE,
AMIRTE, AMSAE-AUS, MSAAA

11918.8

~~10760.24~~

20%: ~~8600~~ 9500

7 Days.