



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 3191B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT PANEL	DENTED	1,221.50	1,213.21
1	FRONT GRILLE	DENTED	479.30	479.30
6	FRONT GRILLE CLIPS @\$3.10	NECESSARY	18.60	18.60
	LESS 10% DISCOUNT		-171.94	-171.11
			1,547.46	1,540.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	150.00
			400.00	150.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		600.00	500.00
	SPRAY PAINTING.		500.00	250.00
	LABOUR TO REMOVE AND REFIT DASHBOARD TO FACILITATE REPAIR.		250.00	150.00
	LABOUR TO REMOVE AND REFIT AIRCON COOLING COIL, BLOWER MOTOR AND TO REFILL REFRIDGERANT.		250.00	150.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	30.00
	SEALANT FOR FRONT PANEL.		60.00	30.00
			1,710.00	1,110.00
	<b>GRAND TOTAL</b>		<b>3,657.46</b>	<b>2,800.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,800.00</b>

Report Ref No. CS/LPC21003328/Qvd3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.