

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21003341/KPA3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800045865

Claimant Vehicle No : SHD69L**Insured Vehicle No :**

SMA2889E

Date of Loss: 10/03/2021

Nature of Claim:

TP

Claim No:

6286719466SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD69L**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No:

M9R8839C002694

Reg. Date: 03/08/2015 (Man. Year: 2015)

Chassis No:

VF1ABL15AUC282224

Colour: Metallic White/Red

Odometer:

765194 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Falken 7 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Falken 7 mm

Rear Right Side:

Sailun 9 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,852.80	1,988.92	863.88	30.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	490.00	7,090.00	93.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,432.80	2,478.92	7,953.88	76.24
Approved Total (Overridden) (S\$)		2,000.00		

(S\$)	10,432.80	2,000.00	8,432.80	80.83
+ GST 7.00/7.00% (S\$)	730.30	140.00	590.30	80.83
Nett Amount (S\$)	11,163.10	2,140.00	9,023.10	80.83
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/03/2021

Date Inspected: 12/03/2021

Estimated Period of Repair: 2.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Distorted	80.80 FL	*80.80 FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
12	1		*SET PARKING AID	Missing / Shorted	700.00 FS	*400.00 FS
13	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
14	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
15	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
16	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
17	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
18	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
19	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,067.00	2,150.80
- List Item Discount on L Items 10.00/10.00% (\$)	214.20	161.88
Total Parts (\$)	2,852.80	1,988.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
Gross Labour Cost (\$\$)			7,580.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >