

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21003343/EVD3Q2
Date: 10/04/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00095162003
Claimant Vehicle No :	SMS7429Y	Insured Vehicle No :	YN2688H
Date of Loss:	09/03/2021	Nature of Claim:	TP
		Claim No:	SNM21D201393/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7429Y	Engine No:	PE21270610
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GL1072K0315396
Reg. Date:	12/03/2020 (Man. Year: 2019)	Odometer:	13587 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50R16	Rear Tyre Size:	205/50R16
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,552.40	10,966.00	3,586.40	24.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,890.00	6,800.00	3,090.00	31.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,442.40	17,766.00	6,676.40	27.31
+ GST 7.00/7.00% (S\$)	1,710.97	1,243.62	467.35	27.31
Nett Amount (S\$)	26,153.37	19,009.62	7,143.75	27.31

INSPECTION

Date of Assignment:	15/03/2021	
Date Inspected:	15/03/2021	Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609042
Estimated Period of Repair:	7.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2021)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS7429Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER,FRONT	Broken	1,211.90 F	*1,211.90 F
2	1		*PLATE RH,SEAL-F,BUMPER	Missing	78.90 F	*78.90 F
3	1		*COVER RH,BUMPER	Missing	30.20 F	*30.20 F
4	1		*RETAINER RH,BUMPER	Broken	17.10 F	*17.10 F
5	2		*GROMMET	Necessary	5.80 F	*5.80 F
6	8		*RIVET	Necessary	32.00 F	*32.00 F
7	1		*MESH,GRILLE	Broken	180.40 F	*180.40 F
8	1		*BRACKET RH,BUMPER	Not Necessary	37.10 F	*- F
9	1		*MOULD RH,FRONT	Broken	251.40 F	*251.40 F
10	1		*MOULD LH,FRONT	Not Necessary	251.40 F	*- F
11	1		*BRACKET,GRILLE-RADIATOR	Not Necessary	95.00 F	*- F
12	6		*RIVET	Necessary	55.20 F	*55.20 F
13	1		*BRACKET RH,FRT BUMPER	Broken	14.50 F	*14.50 F
14	8		*RIVET	Necessary	32.00 F	*32.00 F
15	1		*PANEL RH,FENDER-FRT	Dented	383.70 F	*383.70 F
16	1		*GUARD RH,MUD	Torn	114.30 F	*114.30 F
17	1		*STAY RH,FENDER	Not Necessary	48.30 F	*- F
18	1		*BODY RH,FRONT DOOR	Dented	975.20 F	*975.20 F
19	1		*HINGE RH,DOOR-UPPER	Not Necessary	37.40 F	*- F
20	1		*HINGE RH,DOOR-LOWER	Not Necessary	37.80 F	*- F
21	1		*FASTENER RH-NECESSARY	Necessary	9.20 F	*9.20 F
22	1		*FASTENER WEATHERSTRIP (54 Pcs)	Not Necessary	183.60 F	*- F
23	1		*STRIPE NO 1 RH,BODY SIDE	Necessary	11.00 F	*11.00 F
24	1		*STRIPE NO 3 RH,BODY SIDE	Necessary	12.90 F	*12.90 F
25	1		*MOULD RH,FRT BELT	Not Necessary	96.00 F	*- F
26	1		*SEAT RH,HANDLE-OUT	Not Necessary	5.70 F	*- F
27	2		*GROMMET	Necessary	4.80 F	*4.80 F
28	1		*CHECKER,DOOR	Not Necessary	47.20 F	*- F
29	1		*GROMMET	Necessary	3.80 F	*3.80 F
30	2		*TAPE SEAL	Necessary	4.80 F	*4.80 F
31	2		*FASTENER	Necessary	6.40 F	*6.40 F
32	9		*GROMMET	Necessary	27.00 F	*27.00 F
33	2		*CLIP	Necessary	4.80 F	*4.80 F
34	2		*COVER,HOLE DOOR	Necessary	10.40 F	*10.40 F
35	18		*FASTENER	Necessary	129.60 F	*129.60 F
36	2		*FASTENER	Necessary	4.80 F	*4.80 F
37	1		*BODY RH,DOOR MIRROR	Broken	475.90 F	*475.90 F
38	1		*HOUSING RH,DR MIRROR	Missing	128.40 F	*128.40 F
39	1		*GLASS & HOLDER RH,MIRROR	Not Necessary	282.50 F	*- F
40	1		*COVER (R),HOLE DR MIRROR	Necessary	13.30 F	*13.30 F
41	1		*GARNISH RH,SAIL OUT	Not Necessary	116.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*WHEEL,DISC	Cut	1,196.80 F	*1,196.80 F
43	1		*CAP,CENTER RIM	Not Necessary	21.60 F	*- F
44	1		*VALVE,AIR	Necessary	6.70 F	*6.70 F
45	1		*HUB,WHEEL FRT	Not Necessary	566.70 F	*- F
46	1		*COVER RH,DUST-BRAKE	Not Necessary	31.90 F	*- F
47	1		*KNUCKLE RH,STEERING	Not Necessary	378.10 F	*- F
48	1		*ARM RH,LOWER	Not Necessary	503.90 F	*- F
49	1		*DAMPER RH,FRONT	Not Necessary	392.40 F	*- F
50	1		*BEARING,FRONT STRUT-DAMPER	Not Necessary	55.80 F	*- F
51	1		*DUST COVER-DAMPER	Not Necessary	36.30 F	*- F
52	2		*STOPPER-DAMPER	Not Necessary	58.20 F	*- F
53	1		*RUBBER-SPRING	Not Necessary	23.40 F	*- F
54	1		*UNIT RH,HEADLAMP	Cut	4,759.30 F	*4,759.30 F
55	1		*PROTECTOR RH,HEAD,LAMP	Necessary	102.00 F	*102.00 F
56	1		*TANK,WASHER	Not Necessary	109.80 F	*- F
57	1		*REINF,RAD GRILLE	Broken	133.70 F	*133.70 F
58	1		*FASTENER,MUDGUARD (21 Pcs)	Necessary	63.00 F	*63.00 F
59	3		*FASTENER,MUDGUARD	Necessary	9.00 F	*9.00 F
60	1		*LAMP (R),SIDE TURN BN/GL	Broken	85.80 F	*85.80 F
61	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
62	1		*TIRE (80%)	Torn	450.00 FS	*360.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	14,552.40	10,966.00
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER (1) ,RHF FENDER (0.5) ,RHF DOOR (1),REPAIR RHR DOOR (0.5),RHR FENDER (0.5) AND AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	1,980.00
2	SRPAY FRT BUMPER (1),BONNET (1) ,RHF FENDER (1),RHF DOOR (1),RHF DOOR (1) ,RHR FENDER (1) ,RH SIDE MIRROR COVER (0.25)	New	4,095.00	3,750.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHouc	New	200.00	0.00
4	TRANSFER DOOR MECHANISM (0.5)	New	630.00	0.00
5	REPLACE THE DAMAGE SUSPENSION ITEMS ON THE RHF SECTION (1)	New	945.00	0.00
6	REPLACE THE RHF SPORT RIM & TIRE ,PERFORM WHEEL BALANCING (MIN 80.00)	New	120.00	80.00
7	CONDUCT 4 WHEEL ALIGNMENT (1)	New	560.00	560.00
8	ELECTRICAL CHECK FOR PROPER FUNCTION	New	250.00	150.00
9	REPROGRAM AFTER THE REPAIR WORKS	New	350.00	180.00
10	TO TWO THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP	New	100.00	100.00
Gross Labour Cost (S\$)			9,890.00	6,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >