

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21003344/Qvf3e2	
	8 SHENTON WAY TOWERSINGAPOR		Date	e: 18/03/2021	
	ATTN: WONG WE	E FU	Cod	e: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMX 3344H	Veh. Inspected	SJP 5619E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	S1M035DA	Excess (\$)	0.00	
	Assign From	WONG WEE FU	Assign Date	15/03/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	KMHDU41BR9U720561	Colour	PURPLE	
	Odometer	444507 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	NEXEN	6 mm	
	L/H Front Tyre	205/55 R16	NEXEN	6 mm	
	R/H Rear Tyre	205/55 R16	NEXEN	6 mm	
	L/H Rear Tyre	205/55 R16	NEXEN	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	5. General Information				
	Accident Date	12/03/2021	Inspect Date / Time	15/03/2021 (03:27 PM)	
	Survey held at 160 SIN MING DRIVE #05-07				
	Repairer HIAP LEK AUTOMOBILE TRADING				
5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			

Report Ref No. CS3/ASM21003344/Qvf3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser