

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21003347/T1vf3e2 Ref: 8 SHENTON WAY #24-01 AXA Date: 18/03/2021 **TOWERSINGAPORE 068811** ATTN: WONG WEE FU Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJX 694C **FBP 280A** Veh. Inspected Policy No. GA536166/1 Coverage (\$) 0.00 Claim No. S1M033ZC Excess (\$) 0.00 WONG WEE FU **Assign Date** 15/03/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA MT-09 ABS TRACER Make & Model c.c 847 HIDDEN 2019 Engine No. Year of Reg. JYARN575000009325 **BLUE** Chassis No. Colour Odometer 42860 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 120/70 R17 PIRELLI 5 mm L/H Front Tyre mm 180/55 R17 **PIRELLI** R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S 5. **General Information** 24/02/2021 16/03/2021 ( 01:41 PM ) Inspect Date / Time Accident Date FTA PERFORMANCE PTE LTD Survey held at 8 KAKI BUKIT AVENUE 4, #07-26, PREMIER @ KAKI BUKIT, SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM21003347/T1vf3e2

**Estimate Days of Repair** 

Inspected By

5b.

MOHAMAD TAUFIKH M.MATAI, AMSAE-A

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor