



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving	TPVD MERCEDES (EZ118Z)
Date of Loss	9 March 2021
Time of Loss	16.30
Loss Description	SHC2513M (INSD) rear-end EZ118Z
Comment	<input type="text"/>

### Workshop Details

Total Rebate Amount	<input type="text" value="28475"/>
Nett Loss Amount	\$14,525.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	EZ118Z	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>11/10/2012</div> <div></div>
Mileage	<div>79739</div>	Age of Vehicle	8

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2012</div>
Make	TPVD	<div>MERCEDES BENZ</div>
		<div></div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHONG JIAMING IAN	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	MERCEDES POLICY INFORMATION	C 180 BLUEEFFICIENCY ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="WDD2040312A772404"/>
Engine No		<input type="text" value="27491030013855"/>
Engine Capacity		<input type="text" value="1595"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="43000"/>

CATEGORY Age	FNOL INFORMATION 0	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text"/> ▼
Gender	Unknown	<input type="text"/> ▼
Marital status	Unknown	<input type="text"/> ▼
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

12/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts













Add






Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER	Damaged	0	1345	No		10			1210.5	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER SIDE BRACKETS - L/R	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER RH	Damaged	0	89.95	No		10			80.96	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER CHROME MOULDING - CTR	Damaged	0	241.35	No		10			217.22	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER CHROME MOULDING LH	Necessary	0	141.35	No		10			127.22	Reviewing

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER CHROME MOULDING RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BUMPER REINFORCEMENT	Dented	0	681.95	No		10			613.76	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER TOP GUIDE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL GARNISH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER AIR VENT - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER INNER SHIELD - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER RAIL PANEL GARNISH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT LID	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT M/B STAR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	3		REAR BOOT M/B STAR CLIPS	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BOOT EMBLEM "C180"	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT EMBLEM "7G-TRONIC"	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BOOT W/STRIP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILLAMP - RH	Cut	0	581.6	No		10			523.44	Reviewing
<input type="checkbox"/>		0	1		REAR TAILLAMP PANEL	Serviceable	0	0	No		10			0	Deny






Labour


Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO CHECK REAR ELECTRICAL WIRING	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE, REFIX REAR REVERSE SENSOR	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO RESPRAY UNDERCOATING	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO RESPRAY PAINTING AND ETC	0	200	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	0	200	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		
<input type="checkbox"/>		0	1 SET REAR REVERSE SENSOR (4 PCS)	Reviewing		200	DAMAGED (1PC ONLY)	
<input type="checkbox"/>		0	1 SET REAR BUMPER CLIP	Reviewing		45	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
------	----------	------	--------	---------------------	--------------------	---------	--------



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$3,508.10	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$2,773.10			
Labour		\$0.00		\$490.00			
Miscellaneous		\$0.00		\$245.00			


Submit for Review

<<

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

- Add
- Approve
- Deny
- Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		2800		



Submit for Review