



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 5910X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRT RH DOOR (WCP)	BENT	820.00	820.00
1	FRT RH DOOR OUTER HANDLE (WCP)	CUT	95.00	95.00
1	FRT RH DOOR SIGNAL LAMP (WCP)	CRACKED	115.00	115.00
1	FRT RH DOOR STEP GARNISH (WCP)	CRACKED	165.00	165.00
1	FRT RH DOOR LOWER HINGE (WCP)	TO REPAIR SEE LABOUR	95.00	-
1	FRT RH CORNER PANEL (WCP)	CRACKED	240.00	240.00
1	FRT RH CORNER PANEL SIDE RUBBER (WCP)	TORN	75.00	75.00
1	FRT RH CORNER PANEL TOP COVER (WCP)	CRACKED	95.00	95.00
1	HEADLAMP RH (WCP)	CRACKED	350.00	350.00
1	HEADLAMP LOWER RUBBER (WCP)	TORN	30.00	30.00
1	FRT BUMPER (WCP)	DEFORMED	400.00	400.00
1	FRT BUMPER BRACKET RH (WCP)	BENT	150.00	150.00
1	FOG LAMP RH (WCP)	CUT	280.00	280.00
1	SIDE MIRROR RH (WCP)	CUT	90.00	90.00
1	PETROL TANK BRACKET RH (WCP)	NOT NECESSARY	155.00	-
1	TAIL LAMP LH (WCP)	CRACKED	165.00	165.00
1	TAIL LAMP BRACKET LH (WCP)	NOT NECESSARY	45.00	-
2	REAR NUMBER PLATE BRACKET (WCP)	MISSING	140.00	140.00
2	NUMBER PLATE LAMP (WCP)	MISSING	110.00	110.00
1	AIR CLEANER BOX (WCP)	NOT NECESSARY	290.00	-
1	AIR FILTER (WCP)	NOT NECESSARY	145.00	-
1	FRT SIGNAL LAMP RH (WCP)	CUT	130.00	130.00
1	FRT RH PILLAR ANTENNA (WCP) (ADDITIONAL)	CUT	95.00	95.00
	COST PLUS 10%		427.50	-
			4,702.50	3,545.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	MISSING	35.00	35.00
1	REAR REINFORCEMENT BAR (SN)	BENT	950.00	750.00
1	REAR REINFORCEMENT BAR BRACKET LH (SN)	NOT NECESSARY	250.00	-
1	REAR SIDE ALUMINIUM FRAME LH (SN)	BENT	850.00	650.00

Report Ref No. CS/SMO21003360/T1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR WOODEN PLANK SUPPORT (SN)	CRACKED	1,700.00	1,400.00
1	REAR WOODEN PLANK RUBBER SUPPORT LH (SN)	CUT	180.00	180.00
1	LH SIDE BOARD (SN)	BENT	1,500.00	1,200.00
1	RH SIDE BOARD (SN)	BENT	1,500.00	1,200.00
1	LH SIDE BOARD ALUMINIUM LOWER FRAME (SN)	BENT	650.00	450.00
1	RH SIDE BOARD ALUMINIUM LOWER FRAME (SN)	BENT	650.00	450.00
1	RH REINFORCEMENT BAR (SN)	BENT	950.00	750.00
1	ENGINE OIL (SN)	NOT NECESSARY	150.00	-
			9,365.00	7,065.00
	LABOUR			
	WIRE CHECKING.		30.00	30.00
	TRANSFER DOOR COMPONENT.		100.00	50.00
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF FRT RH DOOR LOWER HINGE.		750.00	700.00
	SPRAY PAINTING.		850.00	700.00
			1,730.00	1,480.00
	GRAND TOTAL		15,797.50	12,090.00
	RECOMMENDED COST OF REPAIRS			12,090.00
	LESS EXCESS			-750.00
	NETT LIABILITY			11,340.00

Report Ref No. CS/SMO21003360/T1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.