



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21003365/Uvf3n2	
			Date: 30/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJJ 6037J	Veh. Inspected	GBB 9078H	
Policy No.	D20MTPV01012563	Coverage (\$)	0.00	
Claim No.	CMTD2100797/LOR	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	15/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTFHT02P300060866	Colour	BROWN	
Odometer	337689 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	GREMAX	6 mm	
L/H Front Tyre	195 R15	GREMAX	6 mm	
R/H Rear Tyre	195 R15	GREMAX	6 mm	
L/H Rear Tyre	195 R15	GREMAX	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2021	Inspection Date	16/03/2021	
Survey held at	SYNERGY BUILDING,KAKI BUKIT #01-44			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	