

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003367/GPA3Q2
Date: 12/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993706
Claimant Vehicle No :	FU5315C	Insured Vehicle No :	SLS9602L
Date of Loss:	08/03/2021	Nature of Claim:	TP
		Claim No:	8148131499SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FU5315C	Engine No:	NF125MDE0000285
Make & Model:	HONDA WAVE 125-S, 125cc	Chassis No:	NF125MD0000285
Reg. Date:	20/02/2002 (Man. Year: 2001)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,547.00	393.30	1,153.70	74.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	300.00	100.00	200.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,847.00	493.30	1,353.70	73.29
Approved Total (Overridden) (S\$)		350.00		

(S\$)	1,847.00	350.00	1,497.00	81.05
+ GST 7.00/7.00% (S\$)	129.29	24.50	104.79	81.05
Nett Amount (S\$)	1,976.29	374.50	1,601.79	81.05
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 17/03/2021

Estimated Period of Repair: 1.0 days

Inspected At: Kivile Enterprise (HQ)
 BLK 3007 UBI RD 1 #01-408
 Singapore 408701

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE GRIP	Torn	30.00 F	*30.00 FL
2	1		*HANDLE BAR	Not Necessary	95.00 F	*- FL
3	1		*SIDE MIRROR	Cut	38.00 F	*38.00 FL
4	1		*IU	Cut	156.00 F	*156.00 FL
5	1		*IU HOLDER	Not Necessary	30.00 F	*- FL
6	1		*FRONT FAIRING	Not Necessary	125.00 F	*- FL
7	1		*SIDE FAIRING	Cut	165.00 F	*165.00 FL
8	1		*FOOTREST	Cut	48.00 F	*48.00 FL
9	1		*FORK REPAIR	Not Necessary	180.00 F	*- FL
10	1		*FORK UNDER BRACKET	Not Necessary	180.00 F	*- FL
11	1		*STEERING BEARING	Not Necessary	95.00 F	*- FL
12	1		*FRONT RING	Not Necessary	155.00 F	*- FL
13	1		*ALIGNMENT	Not Necessary	250.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,547.00	437.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	43.70
Total Parts (\$\$)	1,547.00	393.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	250.00	100.00
2	TOW	New	50.00	0.00
Gross Labour Cost (S\$)			300.00	100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >