

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003368/URS3Q2
Date: 26/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800131152
Claimant Vehicle No :	SMR3817S	Insured Vehicle No :	SLK7000D
Date of Loss:	11/03/2021	Nature of Claim:	TP
		Claim No:	1098992026SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3817S	Engine No:	CJE092025
Make & Model:	AUDI A4, 1.8 TFSI MU (EU6) (A)	Chassis No:	WAUZZZ8K6FA060548
Reg. Date:	12/02/2015 (Man. Year: 2014)	Odometer:	75772 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,310.00	12,560.50	8,749.50	41.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,630.00	1,790.00	52.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,730.00	14,190.50	10,539.50	42.62
Approved Total (Overridden) (S\$)		11,300.00		

(S\$)	24,730.00	11,300.00	13,430.00	54.31
+ GST 7.00/7.00% (S\$)	1,731.10	791.00	940.10	54.31
Nett Amount (S\$)	26,461.10	12,091.00	14,370.10	54.31
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
(S\$)		12,691.00		
Liabe Amount (50.00%) (S\$)		6,345.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,347.50		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent / Buckled	2,880.00 F	*2,880.00 FL
2	1		*BONNET LOCK	Not Necessary	199.00 F	*- FL
3	1		*FRONT BUMPER	Distorted	2,860.00 F	*2,560.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	912.00 F	*- FL
5	1		*FRONT BUMPER SIDE HOLDER N/S	Cracked	125.00 F	*75.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*50.00 FL
7	1		*FRONT BUMPER FOG LAMP N/S	Cracked	285.00 F	*262.00 FL
8	1		*FRONT BUMPER FOG LAMP COVER N/S	Missing	305.00 F	*135.00 FL
9	1		*FRONT BUMPER NOZZLE COVER N/S	Torn	60.00 F	*38.00 FL
10	1		*FRONT BUMPER NOZZLE N/S	Not Necessary	188.00 F	*- FL
11	1		*HEADLAMP N/S	Broken	3,950.00 F	*2,343.00 FL
12	1		*HEADLAMP LOWER BRACKET N/S	Cracked	285.00 F	*106.00 FL
13	1		*FRONT SUPPORT PANEL	Cracked	1,225.00 F	*1,016.00 FL
14	1		*FRONT FENDER N/S	Badly Dented	1,155.00 F	*990.00 FL
15	1		*FRONT FENDER INNER SHIELD N/S	Torn	288.00 F	*240.00 FL
16	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	60.00 F	*50.00 FL
17	1		*FRONT SPORT RIM N/S	Bent	1,200.00 FS	*600.00 FS
18	1		*FRONT LOWER ARM N/S	Serviceable	615.00 F	*- FL
19	1		*FRONT KNUCKLE ARM N/S	Bent	1,155.00 F	*968.00 FL
20	1		*FRONT KNUCKLE ARM BEARING N/S	Damaged	485.00 F	*485.00 FL
21	1		*FRONT LOWER ARM N/S	Repeated	620.00 F	*- FL
22	1		*FRONT TORSION ARM N/S	Twisted	588.00 F	*392.00 FL
23	1		*AIR CON CONDENSER	Not Necessary	890.00 F	*- FL
24	1		*RADIATOR	Not Necessary	920.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,310.00	13,190.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	629.50
Total Parts (\$\$)	21,310.00	12,560.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	60.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
4	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	New	200.00	120.00
5	TO REFILL AIR CON GAS	New	120.00	100.00
6	TO RESET & REPROGRAMME SYSTEM	New	120.00	50.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	600.00
Gross Labour Cost (S\$)			3,420.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >