LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21003370/GVF3E2

Date: 06/04/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MX008840

Claimant Vehicle Curposcoli.

No: SHB6628U Insured Vehicle No: SKP7659P

Date of Loss: 11/03/2021 Nature of Claim: TP Claim No: M2101234

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB6628U

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU400503

Reg. Date: 30/10/2019 (Man. Year: 2019) Chassis No: KMHC851CVLU187517

Colour: Blue Odometer: 134110 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lane 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	419.48	419.48	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	600.00	150.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,180.48	1,030.48	150.00	12.71
+ GST 7.00/7.00% (S\$)	82.63	72.13	10.50	12.71
Nett Amount (S\$)	1,263.11	1,102.61	160.50	12.71

INSPECTION

Date of Assignment: 15/03/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 15/03/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB6628U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Cut	430.90 FL	-	*430.90 FL
2	1		*FRT BUMPER FOG LAMP GARNISH RH	Cut	93.45 FL	-	*93.45 FL
F=Fra	nchise	part. L=ListIt	emDisc.	r			
				Sub Total (S\$)	524.35	524.35	
			- List Item Discount on L Items	20.00/20.00% (S\$)	104.87	104.87	
				Total Parts (S\$)	419.48		419.48
			Report was unsubmitted during	this print-out.			

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount			
Mis	Miscellaneous Items							
1	1	OD/TP Case (Insurer)		11.00	11.00			
			Sub Total (S\$)	11.00	11.00			

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK LIGHTING	New	50.00	0.00
		Gross Labour Cost (S\$)	750.00	600.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >