

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003371/UPA3Q2
Date: 04/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700057645
Claimant Vehicle No :	SMX3369L	Insured Vehicle No :	SFK7071U
Date of Loss:	10/03/2021	Nature of Claim:	TP
		Claim No:	2522511133SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX3369L	Engine No:	G4FGGH672596
Make & Model:	KIA CERATO, 1.6 SUNROOF (A)	Chassis No:	KNAFZ411MJ5729390
Reg. Date:	08/06/2017 (Man. Year: 2017)	Odometer:	62626 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,185.00	6,674.00	8,511.00	56.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	2,750.00	1,640.00	37.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,575.00	9,424.00	10,151.00	51.86
Approved Total (Overridden) (S\$)		7,500.00		

(S\$)	19,575.00	7,500.00	12,075.00	61.69
+ GST 7.00/7.00% (S\$)	1,370.25	525.00	845.25	61.69
Nett Amount (S\$)	20,945.25	8,025.00	12,920.25	61.69
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
Nett Liability (S\$)		9,095.00		
Global Sum Settlement (S\$)		9,000.00		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 10.0 days

Inspected At:

V-tec Asia Automotive Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4, #07-08/09 PREMIER@KB
 Singapore 415875

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NEW)	Distorted	1,500.00 F	*651.00 FL
2	1		*COVER REAR BUMPER LOWER (NEW)	Distorted	580.00 F	*241.00 FL
3	4		*REAR REVERSE SENSOR	Shorted	720.00 FS	*250.00 FS
4	1		*PANEL ASSY TRUNK LID -REAR BOOT	Badly Dented	1,980.00 F	*1,297.00 FL
5	1		*EXHAUST PIPE	Repair	480.00 F	*- FL
6	2		*REAR REFLECTOR	Not Necessary	350.00 F	*- FL
7	1		*CAR PLATE }	Bent	80.00 FS	*40.00 FS
8	1		*CAR PLATE HOLDER }		50.00 FS	*- FS
9	1		*CERATO K3 & KA EMBLEMS	Necessary	180.00 F	*180.00 FL
10	1		*REAR TAILLMP TAILLIGHT (NEW)	N/S Cracked	2,200.00 F	*675.00 FL
11	1		*REAR FLOOR PANEL INSULATOR	Necessary	175.00 FS	*120.00 FS
12	1		*REVERSE CAMERA	Serviceable	320.00 F	*- FL
13	2		*REAR BOOT HINGES	Serviceable	270.00 F	*- FL
14	1		*REAR REINFORCEMENT	Cracked	800.00 F	*318.00 FL
15	2		*REAR BUMPER BRACKET MOUNT	Twisted	280.00 F	*210.00 FL
16	1		*REAR LOCK ASSEMBLY	Bent	410.00 F	*112.00 FL
17	1		*WEATHERSTRIP	Twisted	280.00 F	*145.00 FL
18	1		*REAR END PANEL	Badly Dented	780.00 F	*324.00 FL
19	2		*REAR SUPPORT PANEL BRACKETS	Bent	290.00 F	*90.00 FL
20	1		*LOCK ANTENNA SENSOR	Cracked	180.00 F	*160.00 FL
21	3		*REINFORCEMENT BRACKET TOP	Twisted	150.00 F	*105.00 FL
22	1		*REAR BUMPER LOWER SPOILER BODY KIT	Distorted	1,350.00 F	*1,350.00 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	280.00 F	*121.00 FL
24	1		*REAR FLOOR PANEL	Crumpled /Buckled	1,500.00 F	*981.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,185.00	7,370.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	696.00
Total Parts (\$\$)	15,185.00	6,674.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING TO REAR BUMPER ,COVER REAR BUMPER CENTER ,REVERSE SENSOR ,REAR BOOT & NECESSARY PART	New	1,450.00	1,200.00
2	LABOUR FOR INSTALLATION OF REAR BUMPER ,COVER REAR BUMPER CENTER ,REVERSE SENSOR ,REAR BOOT ,REINFORCEMENT ,REAR BOOT LEVEL & AFFECTED CAR BODY PARTS	New	2,000.00	1,400.00
3	DISMANTLING AND INSTALLATION OF TAILLIGHT ,UPHOLSTERY ,GARNISH	New	380.00	80.00
4	REWIRING ,TESTING AND COMMISSIONING OF REVERSE SENSOR ,REAR REVERSE CAM	New	250.00	50.00
5	4 WHEELS 3D ALIGNMENT	New	180.00	0.00
6	TO CHECK WIRING	New	50.00	20.00
7	TO R&R REVERSE SENSOR	New	80.00	0.00
Gross Labour Cost (S\$)			4,390.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >