

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003372/BPS3Q2
Date: 14/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100507263
Claimant Vehicle No :	GBJ5646C	Insured Vehicle No :	SLB4482M
Date of Loss:	09/03/2021	Nature of Claim:	TP
		Claim No:	6550186967SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5646C		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2856642
Reg. Date:	31/05/2019 (Man. Year: 2019)	Chassis No:	JTFAT35Y40K213279
Colour:	White	Odometer:	43694 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	155/15	Rear Tyre Size:	155/12
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,182.72	3,790.09	4,392.63	53.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	2,050.00	2,750.00	57.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,982.72	5,840.09	7,142.63	55.02
Approved Total (Overridden) (S\$)		5,800.00		

(S\$)	12,982.72	5,800.00	7,182.72	55.33
+ GST 7.00/7.00% (S\$)	908.79	406.00	502.79	55.33
Nett Amount (S\$)	13,891.51	6,206.00	7,685.51	55.33
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,933.45		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 7.0 days

Inspected At:

160 SIN MING DR

#01-14

Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Repair	986.00 FL	*- FL
2	1		*FRONT PANEL MOULDING	No such part	197.00 FL	*- FL
3	1		*FRONT PANEL EMBLEM DYNA	Necessary	65.00 FL	*65.00 FL
4	1		*FRONT CORNER PANEL LH	Broken	298.00 FL	*298.00 FL
5	1		*FRONT GRILLE	Cracked	484.00 FL	*388.85 FL
6	1		*FRONT GRILLE LOGO	Necessary	68.00 FL	*68.00 FL
7	1		*HEADLAMP LH	Broken	988.80 FL	*745.00 FL
8	1		*FRONT BUMPER	Broken	386.20 FL	*386.20 FL
9	1		*FRONT BUMPER BRACKET	N/S Bent	288.00 FL	*51.00 FL
10	1		*FRONT FOG LAMP COVER LH	Broken	78.00 FL	*78.00 FL
11	1		*FRONT DOOR LH	Dented	1,208.10 FL	*1,208.10 FL
12	1		*FRONT DOOR WEATHERSTRIP	Not Damaged	210.00 FL	*- FL
13	1		*FRONT DOOR LOCK	Not Damaged	238.00 FL	*- FL
14	1		*FRONT DOOR LOCK ACTUTOR	Not Damaged	158.00 FL	*- FL
15	1		*FRONT DOOR LOCK STRICKER	Not Damaged	58.10 FL	*- FL
16	2		*FRONT DOOR HINGE	Not Damaged	206.60 FL	*- FL
17	1		*FRONT DOOR INNER TRIM BOARD	Not Damaged	598.20 FL	*- FL
18	1		*FRONT DOOR PILLAR OUTER	Repair	485.30 FL	*- FL
19	1		*FRONT WINDSCREEN RUBBER	Not Necessary	287.20 FL	*- FL
20	1		*FRONT STEP PANEL LH	Broken	248.00 FL	*248.00 FL
21	1		*FRONT STEP GARNISH LH	Not Necessary	298.70 FL	*- FL
22	1		*A/C CONDENSER	Broken	753.10 FL	*651.00 FL
23	1		*A/C CONDENSER BRACKET	Bent	332.00 FL	*236.30 FL
24	1		*A/C FAN ASSY	Broken	350.00 FL	*350.00 FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*FRONT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
27	1		*FRONT CORNER PANEL CLIPS	Necessary	100.00 FS	*30.00 FS
28	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*FRONT DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
31	1		*FRONT DOOR INNER TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
32	1		*FRONT DOOR SPEAKER	Not Necessary	210.00 FS	*- FS
33	1		*FRONT DOOR PILLAR OUTER SEALANT	Not Necessary	100.00 FS	*- FS
34	1		*FRONT DOOR COMPANY STICKER	Necessary	40.00 FS	*40.00 FS
35	1		*FRONT STEP PANEL SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT STEP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*A/C FLUID	Necessary	120.00 FS	*40.00 FS
38	1		*FRONT NUMBER PLATE	Not Damaged	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,500.30	4,983.45
- List Item Discount on L Items 25.00/25.00% (S\$)	2,317.58	1,193.36
Total Parts (S\$)	8,182.72	3,790.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R FRONT DOOR COMPONENT	New	150.00	80.00
2	R&R FRONT WINDSCREEN	New	250.00	0.00
3	R&R FRONT DASHBOARD	New	450.00	0.00
4	R&R A/C CONDENSER	New	150.00	80.00
5	CHECK WIRING	New	100.00	30.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEATING	New	1,600.00	800.00
8	RUST PROOFING	New	200.00	60.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			4,800.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >