

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD  
15 UBI ROAD 4  
SINGAPORE 408623  
6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0105/21

DATE : 13-MAR-2021

BUDGET DIRECT INSURANCE \*\*DO NOT USE. USE A015\*\*

190 CLEMENCEAU AVENUE

#03-01 SINGAPORE SHOPPING CENTRE

S(239924)

TEL : 62212111

FAX :

OWNER'S NAME : MR LEE YONG MING JORDAN

ADDRESS : BLK 290A BUKIT BATOK STREET 24

#16-83

S(652290)

TELEPHONE NO : 92979709

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : \*

VEHICLE NO : SML271S

MODEL CODE : BDTARCZB17EWA---K19

MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2019

ENGINE NO : HR16942651C

CHASSIS NO : MNTBBAB17Z0035737

MILEAGE : 331149 KM

DATE IN : 13/03/2021

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 13/03/2021

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SML271S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW FRONT BUMPER.	450.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME INCLUDE FRONT BUMPER SKIRTING.	550.00	
		TOTAL LABOUR CHARGES	1000.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SML271S

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			30.00	
2	FOG LAMP GARNISH RH	62256-3ST0B	130.10			
3	FRONT BUMPER FASCIA	62022-3SN5H	597.20			
SUB TOTAL			727.30	0.00	30.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			145.46	0.00	0.00	
GRAND TOTAL			581.84	0.00	30.00	
OVERALL TOTAL			611.84			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SML271S

-----  
TOTAL LABOUR CHARGES           1000.00  
TOTAL SPARE PARTS CHARGES       611.84  
-----  
GRAND TOTAL                   1611.84 \*  
-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

-----  
NAME                   :  
SURVEYED DATE         :  
AUTHORIZED DATE       :  
EXCESS CLAUSE         :       0.00  
LIABILITY             :       0.00  
REMARKS               :

PLS NOTE : This estimate is based on visual inspection of the  
          affected vehicle. Should we require further labour  
          charges & spare parts in the process of repairs, we  
          shall inform you accordingly.