

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003379/QPA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700036511-03
Claimant Vehicle No :	SGR1759K	Insured Vehicle No :	GM1706P
Date of Loss:	15/03/2021	Nature of Claim:	TP
		Claim No:	0890861214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR1759K	Engine No:	4G18HS0620
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A7U005452
Reg. Date:	01/02/2007 (Man. Year: 2006)	Odometer:	227581 km
Colour:	White		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Wonder 6 mm	Rear Left Side:	Wonder 6 mm
Front Right Side:	Wonder 6 mm	Rear Right Side:	Wonder 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,360.40	4,459.20	9,901.20	68.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,120.00	2,830.00	2,290.00	44.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,480.40	7,289.20	12,191.20	62.58
Approved Total (Overridden) (S\$)		1,500.00		

Nett Amount (S\$)	19,480.40	1,500.00	17,980.40	92.30
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
Nett Liability (S\$)		2,300.00		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 16/03/2021

Estimated Period of Repair: 8.0 days

Inspected At: A-Tec Motorz Pte Ltd (HQ)
39 Woodlands Close #02-43, Mega@Woodlands
Singapore 737856

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	629.00 FL	*629.00 FL
2	2		*FRONT BONNET HINGES	Serviceable	116.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Jammed	85.00 FL	*85.00 FL
4	2		*FRONT HEADLAMPS	Cracked (1 PCS ONLY)	1,172.00 FL	*586.00 FL
5	2		*FRONT GRILLE MESHES	Cracked (1 PCS ONLY)	178.00 FL	*89.00 FL
6	1		*FRONT GRILLE FRAME	Cracked	156.00 FL	*156.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	42.00 FL	*42.00 FL
8	1		*FRONT BUMPER	Crumpled	743.00 FL	*650.00 FL
9	1		*FRONT BUMPER LOWER GRILLE	Crumpled	116.00 FL	*116.00 FL
10	1		*FRONT BUMPER REINFORCEMENT	Bent	134.00 FL	*134.00 FL
11	2		*FRONT BUMPER SIDE RETAINERS	Broken	82.00 FL	*82.00 FL
12	2		*FRONT BUMPER SIDE GRILLES	Serviceable	76.00 FL	*- FL
13	1		*FRONT NUMBER PLATE GARNISH	Scratched	76.00 FL	*76.00 FL
14	2		*FRONT FENDERS	Repair	972.00 FL	*- FL
15	2		*FRONT FENDER INNER SHIELDS	Serviceable	214.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Repair	595.00 FL	*- FL
17	1		*FRONT BRACE PANEL	Serviceable	30.00 FL	*- FL
18	1		*HORN	Serviceable	86.00 FL	*- FL
19	1		*AIR CON CONDENSER	Serviceable	1,121.00 FL	*- FL
20	1		*AIR CON ELECTRIC FAN ASSY	Serviceable	921.00 FL	*- FL
21	1		*RADIATOR	Serviceable	845.00 FL	*- FL
22	1		*AIR INTAKE DUCT	Crumpled	132.00 FL	*132.00 FL
23	1		*FRONT WIPER TANK	Serviceable	94.00 FL	*- FL
24	1		*REAR BOOT LID	Dented	595.00 FL	*595.00 FL
25	2		*REAR BOOT HINGES	Serviceable	136.00 FL	*- FL
26	1		*REAR BOOT LOCK	Jammed	132.00 FL	*132.00 FL
27	1		*REAR BOOT LOGO	Necessary	48.00 FL	*48.00 FL
28	1		*REAR BOOT WEATHERSTRIP	Serviceable	139.00 FL	*- FL
29	1		*REAR BOOT C&C EMBLEM	Necessary	28.00 FL	*28.00 FL
30	1		*REAR BOOT LANCER EMBLEM	Necessary	38.00 FL	*38.00 FL
31	2		*REAR TAILLAMPS	Scratched	910.00 FL	*820.00 FL
32	1		*REAR END PANEL	Repair	435.00 FL	*- FL
33	1		*REAR END PANEL INNER GARNISH	Serviceable	155.00 FL	*- FL
34	1		*REAR BUMPER	Crumpled	743.00 FL	*640.00 FL
35	1		*REAR BUMPER TOP BEAM	Serviceable	186.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
37	2		*REAR BUMPER SIDE RETAINER	Broken	96.00 FL	*96.00 FL
38	1		*REAR FLOOR PANEL	Repair	955.00 FL	*- FL
39	1		*REAR FLOOR BOARD	Serviceable	189.00 FL	*- FL
40	1		*REAR EXHAUST SILENCER	Serviceable	465.00 FL	*- FL
41	2		*REAR EXHAUST MOUNTINGS	Serviceable	64.00 FL	*- FL
42	1		*REAR FENDER R/H	Serviceable	755.00 FL	*- FL
43	2		*REAR FENDER INNER TRIM	Serviceable	572.00 FL	*- FL
44	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
45	1		*FRONT NUMBER PLATE	Scratched	50.00 FS	*50.00 FS
46	2		*SETS FRONT FENDER INNER SHIELD CLIP	Serviceable	90.00 FS	*- FS
47	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
48	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,891.00	5,504.00
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,530.60	1,044.80
Total Parts (\$\$)	14,360.40	4,459.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING ,LIGHTING AND RESETTING HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE, REFIT ,REPLACED DAMAGED LAMPS AND CHECK UP REAR ELECTRICAL WIRING	New	80.00	30.00
3	TO REMOVE AND REFIT INNER GARNISHES ,INNER TRIM TO ASSIST REPAIR	New	150.00	50.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	30.00
5	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY TO ASSIST REPAIR	New	80.00	50.00
6	TO REMOVE AND REPLACE AIR-CON CONDENSER ,VACUUM ,REFILL GAS AND CONDUCT LEAKAGE TEST	New	180.00	100.00
7	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	200.00	40.00
8	TO PROVIDE LABOUR CHARGES ,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIR INCLUDING CUT AND WELD, REALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,200.00
9	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHARGES BODY PARTS ,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	2,000.00	1,300.00
Gross Labour Cost (\$\$)			5,120.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >