

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003384/KPA3Q2
Date: 04/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070152889
Claimant Vehicle No :	SMC1785S	Insured Vehicle No :	SJK8661M
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	0144648621SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1785S		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T (A)	Engine No:	HRA2640648A
Reg. Date:	27/06/2018 (Man. Year: 2018)	Chassis No:	SJNFEAJ11U2313573
Colour:	Metallic Red	Odometer:	38470 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,964.15	942.32	4,021.83	81.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,100.00	1,950.00	63.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,014.15	2,042.32	5,971.83	74.52
+ GST 7.00/7.00% (S\$)	560.99	142.96	418.03	74.52

Nett Amount (S\$)	8,575.14	2,185.28	6,389.86	74.52
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,401.28		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 17/03/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Goldbell Engineering Pte Ltd
 Blk 5035
 Ang Mo Kio Industrial Park 2
 #01-367
 Singapore 569538

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,690.00 FL	*796.70 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	45.00 FL	*- FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	45.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Serviceable	285.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	1,365.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT STAY LH	Repair	276.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT STAY RH	Repair	276.00 FL	*- FL
8	1		*REAR END PANEL	Repair	1,040.00 FL	*- FL
9	1		*REAR BUMPER TOWING COVER	Mtg Cracked	71.50 FL	*28.10 FL
10	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
11	1		*SET REAR REVERSE SENSOR	Dented	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,473.50	1,024.80
- List Item Discount on L Items 10.00/10.00% (\$)	509.35	82.48
Total Parts (\$)	4,964.15	942.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIX & REPAIR AFFECTED DAMAGED PARTS INCLUDING KNOCK OUT ,WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	1,800.00	600.00
2	TO REMOVE AND REPLACE REVERSE SENSOR	New	100.00	50.00
3	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	0.00
4	TO PUTTY ,CLEAN ,SPRAY PAINT AND POLISH ETC	New	1,050.00	450.00
Gross Labour Cost (\$\$)			3,050.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >