

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21003388/DEA3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SHC7589L **Insured Vehicle No :** SML955C
 Date of Loss: 10/03/2021 Nature of Claim: TP Claim No: MFL2021D0001150

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC7589L**
 Make & Model: HYUNDAI AE IONIQ HEV DCT, 1.6 (A) Engine No: G4LEKU299932
 Reg. Date: 06/08/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU165177
 Colour: Yellow Odometer: 129221 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,797.28	7,107.12	3,690.16	34.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,380.00	1,940.00	3,440.00	63.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,177.28	9,047.12	7,130.16	44.08
+ GST 7.00/7.00% (S\$)	1,132.41	633.30	499.11	44.08
Nett Amount (S\$)	17,309.69	9,680.42	7,629.27	44.08
+ Loss of Use (8.0 x S\$40.00/day) (S\$)		320.00		
+ Car Rental (8.0 x S\$128.40/day) (S\$)		1,027.20		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		11,115.07		

INSPECTION

Date of Assignment: 15/03/2021
 Date Inspected: 16/03/2021 Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ)
 Estimated Period of Repair: 6.0 days Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
 Singapore 575644

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Dec 2021)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7589L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted / Cut	459.40 FL	*459.40 FL
2	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR FENDER (RH)	Dented	1,768.30 FL	*1,768.30 FL
4	2		*REAR FENDER SHIELD REAR PIECE (LH/RH)	Not Necessary	173.60 FL	*- FL
5	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
6	1		*REAR FENDER CORNER INNER UPPER GARNISH (RH)	Not Necessary	486.70 FL	*- FL
7	1		*REAR DOOR (RH)	Dented	1,789.90 FL	*1,789.90 FL
8	1		*REAR DOOR RUBBER (RH)	Serviceable	280.00 FL	*- FL
9	1		*REAR DOOR OUTER HANDLE (RH)	Not Necessary	124.80 FL	*- FL
10	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
11	1		*REAR DOOR TRIM BOARD (RH)	Not Necessary	613.60 FL	*- FL
12	1		*REAR DOOR PROTECTOR (RH)	Cut	166.20 FL	*166.20 FL
13	1		*REAR WHEELBEARING & HUB ASSY	Damaged	554.00 FL	*554.00 FL
14	1		*REAR TRAILING ARM (RH)	Distorted	265.40 FL	*265.40 FL
15	1		*REAR ASSIST (RH)	Distorted	227.90 FL	*227.90 FL
16	1		*REAR SHOCK ABSORBER (RH)	Distorted	230.50 FL	*230.50 FL
17	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
18	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
19	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
20	1		*REAR CROSSMEMBER	Not Necessary	1,468.70 FL	*- FL
21	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
22	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
23	1		*REAR UPPER ARM (RH)	Distorted	239.50 FL	*239.50 FL
24	1		*REAR LOWER ARM (RH)	Distorted	393.10 FL	*393.10 FL
25	1		*REAR KNUCKLE ARM (RH)	Distorted	538.10 FL	*538.10 FL
26	1		*REAR DOOR TEL NO.STICKER (LH/RH)	Not fitted	10.00 FS	*- FS
27	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
28	1		*ROCKER PANEL PANEL GARNISH (RH)	Bent / Cut	715.60 FL	*715.60 FL
29	1		*REAR WHEEL RIM (RH)	Distorted	1,124.20 FL	*1,124.20 FL
30	1		*REAR WHEEL HUB CAP	Cut	289.80 FL	*289.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,474.10	8,863.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,676.82	1,756.78
Total Parts (\$\$)	10,797.28	7,107.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
9	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	150.00
10	RE-SET REAR ABS SYSTEM	New	400.00	0.00
11	REMOVE/REFIX FUEL TANK	New	80.00	0.00
12	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
13	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
14	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
15	FOUR WHEEL ALIGNMENT	New	120.00	60.00
16	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (\$\$)			5,380.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >