

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21003391/AGA3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MPC0004201
Claimant Vehicle No :	SMP8482B	Insured Vehicle No :	SFM668J
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0001136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8482B		
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Engine No:	2ZR0E23916
Reg. Date:	18/10/2019 (Man. Year: 2019)	Chassis No:	ZWR800401836
Colour:	Black	Odometer:	167463 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,897.12	7,353.15	5,543.97	42.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,670.00	630.00	27.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,197.12	9,023.15	6,173.97	40.63
Approved Total (Overridden) (S\$)		7,200.00		

Nett Amount (S\$)	15,197.12	7,200.00	7,997.12	52.62
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,007.45		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 16/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Auto Bullox Pte Ltd (HQ)
 53 UBI AVE 1, #01-19 PAYA UBI INDUSTRIAL PARK
 Singapore 408934

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2021)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP8482B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,217.90 FL	*1,025.00 FL
2	1		*FRONT FENDER LH	Distorted	987.90 FL	*788.00 FL
3	1		*FRONT DOOR LH	Not Necessary	1,532.60 FL	*- FL
4	1		*FOGLAMP LH	Chipped	360.00 FL	*360.00 FL
5	1		*FOGLAMP CHROME MOULDING	Cut	185.00 FL	*185.00 FL
6	1		*FRONT GRILLE ASSY	Chipped	1,718.90 FL	*798.00 FL
7	1		*BUMPER RETAINER LH	Necessary	95.00 FL	*95.00 FL
8	1		*FRONT RIM LH	Cut	350.00 FL	*350.00 FL
9	1		*HEADLAMP SUPPORT PANEL LH	Dented	125.00 FL	*125.00 FL
10	1		*FRONT SENSOR	Damaged	250.00 FL	*250.00 FL
11	1		*FRONT BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
12	1		*FRONT HEADLAMP LH	Cracked	3,738.90 FL	*3,291.00 FL
13	1		*FENDER INNER SHIELD LH	Torn	171.90 FL	*171.90 FL
14	1		*ABSORBER LH	Bent	472.30 FL	*472.30 FL
15	1		*LOWER ARM	Bent	1,202.30 FL	*579.00 FL
16	1		*STABILIZER	Not Necessary	180.00 FL	*- FL
17	1		*KNUCKLE ARM	Damaged	663.40 FL	*565.00 FL
18	2		*WHEEL ALIGNMENT	Necessary	100.00 FL	*100.00 FL
19	1		*REINFORCEMENT FOAM	Cracked	185.00 FL	*185.00 FL
20	1		*REINFORCEMENT	Bent	780.00 FL	*419.00 FL
21	1		*SUPPORT PANEL	Repair	1,760.30 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	16,121.40	9,804.20
- List Item Discount on L Items 20.00/25.00% (\$\$)	3,224.28	2,451.05
Total Parts (\$\$)	12,897.12	7,353.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE ,REFIX FRONT SENSOR	New	50.00	50.00
2	PANEL BEATING ,REMOVE REPLACE ABOVE PARTS	New	1,000.00	700.00
3	SPRAY PAINTING ACCIDENT AREA	New	1,000.00	700.00
4	REMOVE AND REFIX UNDERCARRIAGE	New	250.00	220.00
Gross Labour Cost (S\$)			2,300.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >