

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21003399/QPS3Q2

Date:

18/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SLG5090C

Date of Loss: 12/03/2021

Policy No:

1800112182

Insured Vehicle No :

SME2864E

Nature of Claim:

TP

Claim No:

9168842517SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLG5090C**

Make & Model: MITSUBISHI LANCER, 1.5 GLX (A)

Reg. Date: 03/10/2016 (Man. Year: 2016)

Colour: Blue

Engine Capacity: 1590 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 4A92CH9013

Chassis No: JMYSRCY1AGU004692

Odometer: 107010 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Front Left Side: Maxxis 6 mm

Front Right Side: Maxxis 6 mm

Rear Tyre Size: 205/60 R16

Rear Left Side: Maxxis 6 mm

Rear Right Side: Maxxis 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,564.93	4,549.34	3,015.59	39.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	2,150.00	1,390.00	39.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,104.93	6,699.34	4,405.59	39.67
Approved Total (Overridden) (S\$)		5,350.00		

(S\$)	11,104.93	5,350.00	5,754.93	51.82
+ GST 7.00/7.00% (S\$)	777.35	374.50	402.85	51.82
Nett Amount (S\$)	11,882.28	5,724.50	6,157.78	51.82
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		6,611.50		

INSPECTION

Date of Assignment: 15/03/2021

Date Inspected: 15/03/2021

Estimated Period of Repair: 6.0 days

Inspected At: Kgc Workshop Pte Ltd (AMK)
14 Ang Mo Kio Street 63, Blk B
Singapore 569116

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RHS	Dented	921.50 FL	*921.50 FL
2	1		*FRONT DOOR WEATHERSTRIP RHS	Serviceable	198.00 FL	*- FL
3	1		*REAR DOOR RHS	Dented	895.60 FL	*895.60 FL
4	1		*REAR DOOR WINDOW MOULDING RHS	Necessary	144.00 FL	*144.00 FL
5	1		*REAR DOOR FRAME RHS 7410A170XA	Necessary	55.00 FL	*55.00 FL
6	1		*REAR DOOR WEATHERSTRIP RHS	Crumpled	198.00 FL	*152.00 FL
7	1		*REAR DOOR UPPER HINGE RHS	Bent	65.00 FL	*65.00 FL
8	1		*REAR DOOR LOWER HINGE RHS	Bent	65.00 FL	*65.00 FL
9	1		*REAR DOOR LOCK RHS	Jammed	244.50 FL	*244.50 FL
10	1		*REAR DOOR OUTER HANDLE RHS	Serviceable	122.00 FL	*- FL
11	1		*REAR DOOR ELECTRICAL WINDOW REGULATOR RHS	Bent	265.00 FL	*265.00 FL
12	1		*REAR DOOR WINDOW MOTOR RHS	Serviceable	251.00 FL	*- FL
13	1		*REAR DOOR WATER SHIELD RHS 7265A036	Serviceable	55.00 FL	*- FL
14	1		*REAR DOOR TRIM RHS	Crumpled	455.80 FL	*455.80 FL
15	1		*REAR DOOR SPEAKER RHS	Cracked	255.00 FL	*210.00 FL
16	1		*REAR SIDE PANEL RHS 5301C346	Crumpled	785.20 FL	*785.20 FL
17	1		*REAR FENDER INNER SHIELD RHS	Serviceable	65.80 FL	*- FL
18	1		*REAR ABSORBER SET RHS	Serviceable	785.00 FL	*- FL
19	1		*REAR LOWER ARM RHS	Serviceable	328.00 FL	*- FL
20	1		*REAR WHEEL BEARING AND HUB RHS	Jammed	374.00 FL	*374.00 FL
21	1		*REAR BUMPER	Serviceable	785.60 FL	*- FL
22	1		*REAR BUMPER RETAINER RHS	Serviceable	28.00 FL	*- FL
23	1		*CENTRE DOOR PILLAR	Serviceable	385.70 FL	*- FL
24	1		*SET DOOR HINGE CLIPS	Serviceable	50.00 FS	*- FS
25	1		*REAR RIM RHS	Scratched	380.00 FS	*380.00 FS
26	1		*REAR TYRE RHS	Serviceable	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,337.70	5,012.60
- List Item Discount on L Items 10.00/10.00% (\$)	772.77	463.26
Total Parts (\$)	7,564.93	4,549.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS	New	1,500.00	1,200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	1,500.00	700.00
3	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR	New	150.00	60.00
4	TRANSFER OF EXISTING REAR DOOR MECHANISM TO NEW DOOR	New	150.00	60.00
5	WHEEL ALIGNMENT	New	80.00	60.00
6	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	80.00	30.00
7	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	40.00
Gross Labour Cost (S\$)			3,540.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >