

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21003400/APS3Q2
Date: 28/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070147480
Claimant Vehicle No :	SDL9786X	Insured Vehicle No :	SKC754L
Date of Loss:	13/03/2021	Nature of Claim:	TP
		Claim No:	1099092065SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDL9786X		
Make & Model:	HONDA CR-V, 1.5 (A)	Engine No:	L15BG2221017
Reg. Date:	18/10/2019 (Man. Year: 2019)	Chassis No:	MRHRW1880KP000049
Colour:	Silver	Odometer:	15107 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/60 R18	Rear Tyre Size:	225/60 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,567.12	3,551.28	7,015.84	66.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,170.00	1,710.00	59.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,447.12	4,721.28	8,725.84	64.89
Approved Total (Overridden) (S\$)		3,700.00		

Nett Amount (S\$)	13,447.12	3,700.00	9,747.12	72.48
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,307.45		
Global Sum Settlement (S\$)		4,300.00		

INSPECTION

Date of Assignment: 16/03/2021

Date Inspected: 17/03/2021

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (TOP)	Deformed	586.20 FL	*586.20 FL
2	1		*FRONT BUMPER (LOWER)	Deformed	530.80 FL	*530.80 FL
3	2		*FRONT BUMPER SENSOR RH	Damaged (1 PCS ONLY)	296.40 FL	*148.20 FL
4	2		*FRONT BUMPER SENSOR HOLDER RH	Damaged (1 PCS ONLY)	138.40 FL	*69.20 FL
5	1		*FRONT BUMPER SENSOR WIREHARNESS	Not Necessary	327.70 FL	*- FL
6	2		*FRONT BUMPER FOGLAMP RH	Cracked	685.20 FL	*342.60 FL
7	1		*FRONT BUMPER FOGLAMP MOULDING (CHROME) C/W GARNISH RH	Not Necessary	84.60 FL	*- FL
8	1		*FRONT BUMPER FOGLAMP HOUSING RH	Cracked	19.20 FL	*19.20 FL
9	1		*FRONT BUMPER FOGLAMP WIREHARNESS	Not Necessary	210.30 FL	*- FL
10	1		*FRONT BUMPER LOWER PROTECTOR	Not Necessary	89.40 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER	O/S Cracked	39.60 FL	*19.80 FL
12	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	602.40 FL	*- FL
13	1		*FRONT BUMPER BEAM	Not Necessary	196.30 FL	*- FL
14	1		*FRONT NUMBER PLATE HOLDER GARNISH	Not Necessary	149.20 FL	*- FL
15	1		*HEADLAMP	O/S Cracked	3,672.80 FL	*1,836.40 FL
16	1		*HEADLAMP LOWER BRACKET	O/S Cracked	72.80 FL	*36.40 FL
17	1		*GRILLE LOGO	Not Necessary	29.50 FL	*- FL
18	1		*GRILLE LOGO GARNISH	Not Necessary	234.50 FL	*- FL
19	1		*CENTRE GRILLE	Not Necessary	264.70 FL	*- FL
20	2		*BONNET LOCK CABLE	Cut	55.20 FL	*55.20 FL
21	2		*BONNET LOCK	Not Necessary	338.80 FL	*- FL
22	1		*FRONT SUPPORT PANEL	Dented	602.90 FL	*602.90 FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	95.60 FL	*- FL
24	1		*FRONT SUPPORT PANEL BOTTOM COVER GAR	Not Necessary	34.20 FL	*- FL
25	1		*AIRCON CONDENSOR	Not Necessary	917.20 FL	*- FL
26	1		*FRONT FENDER RH	Not Necessary	675.40 FL	*- FL
27	2		*FRONT FENDER INNER COWLING	Not Necessary	311.20 FL	*- FL
28	2		*FRONT FENDER ARCD GARNISH	Not Necessary	134.40 FL	*- FL
29	1		*FRONT WHEEL HOUSE SUPPORT PANEL	Repair	404.80 FL	*- FL
30	1		*FRONT WASHER TANK	Deformed	79.70 FL	*79.70 FL
31	1		*FRONT WASHER TANK MOTOR	Not Necessary	46.90 FL	*- FL
32	1		*FRONT WASHER TANK MOTOR WIRE HARNESS	Not Necessary	107.60 FL	*- FL
33	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
34	1		*SET FRONT BUMPER (TOP) CLIP	Necessary	80.00 FS	*20.00 FS
35	1		*SET FRONT BUMPER (LOWER) CLIP	Necessary	80.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET FRONT BUMPER COVER GARNISH CLIP	Necessary	60.00 FS	*10.00 FS
37	1		*SET FRONT NUMBER PLATE HOLDER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
38	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
39	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	80.00 FS	*- FS
40	1		*SET FRONT SUPPORT PANEL BOTTOM COVER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
41	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
42	1		*SET FRONT FENDER ARCD GARNISH CLIP	Not Necessary	80.00 FS	*- FS
43	1		*SET FRONT GRILLE CLIP	Not Necessary	60.00 FS	*- FS
44	1		*COOLANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,973.90	4,416.60
- List Item Discount on L Items 20.00/20.00% (\$)	2,406.78	865.32
Total Parts (\$)	10,567.12	3,551.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT,REMOVE AND REPLACE PARTS	New	1,200.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	400.00
3	REFOCUS HEADLAMP BEAM	New	80.00	0.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	REMOVE AND REFIX FRONTSensor AND DISTANCE SETTING	New	80.00	50.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	120.00	0.00
Gross Labour Cost (S\$)			2,880.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >