

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21003402/AGS3Q2**Date:** 18/01/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SFE8000A **Insured Vehicle No :** SLN4755M
 Date of Loss: 15/03/2021 Nature of Claim: TP Claim No: MFL2021D0001138

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFE8000A**
 Make & Model: TOYOTA ALPHARD, 2.5 (A) Engine No: 2AR2225648
 Reg. Date: 02/12/2019 (Man. Year: 2019) Chassis No: AYH300090366
 Colour: Bronze Odometer: 147777 km
 Engine Capacity: 2493 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,192.58	16,959.12	19,233.46	53.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,498.00	2,860.00	4,638.00	61.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,690.58	19,819.12	23,871.46	54.64
Approved Total (Overridden) (S\$)		15,000.00		
Nett Amount (S\$)	43,690.58	15,000.00	28,690.58	65.67
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		15,877.45		
Global Sum Settlement (S\$)		15,850.00		

INSPECTION

Date of Assignment: 16/03/2021
 Date Inspected: 16/03/2021 Inspected At: Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @
 KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2021)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFE8000A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,402.40 FL	*1,785.00 FL
2	1	*FRONT BUMPER FOG LAMP LH	Cracked	516.10 FL	*267.00 FL
3	1	*FRONT BUMPER FOG LAMP HOUSING LH	Cut	81.20 FL	*81.20 FL
4	1	*FRONT BUMPER FOG LAMP COVER CHROME LH	Cut	231.20 FL	*114.00 FL
5	1	*FRONT BUMPER TOWING COVER LH	Deformed	28.60 FL	*28.60 FL
6	1	*FRONT BUMPER LOWER GRILLE	Necessary	148.50 FL	*148.50 FL
7	1	*FRONT BUMPER SIDE RETAINER	N/S Damaged	206.80 FL	*103.40 FL
8	1	*FRONT BUMPER REINFORCEMENT	Bent	466.40 FL	*466.40 FL
9	1	*FRONT BUMPER SPONGE	Cracked	99.30 FL	*99.30 FL
10	1	*FRONT BUMPER BOTTOM COVER	Deformed	155.80 FL	*155.80 FL
11	2	*FRONT BUMPER SENSOR	Damaged (1 PCS ONLY)	835.20 FL	*285.00 FL
12	2	*FRONT BUMPER SENSOR HOLDER	Damaged (1 PCS ONLY)	64.40 FL	*32.20 FL
13	1	*FRONT GRILLE C/W MOULDING	Cracked	2,354.01 FL	*1,650.00 FL
14	1	*FRONT GRILLE LOGO	Not Necessary	1,673.50 FL	*- FL
15	4	*FRONT GRILLE TOP RUBBER	Not Necessary	120.80 FL	*- FL
16	1	*FRONT GRILLE SIDE MOULDING (CHROME)	N/S Cracked	503.00 FL	*251.50 FL
17	1	*FRONT WINDSCREEN SIDE MOULDING LH	Not Necessary	132.10 FL	*- FL
18	1	*HEADLAMP (LED)	N/S Cracked	7,593.80 FL	*3,796.90 FL
19	1	*FRONT BONNET	Buckled	855.60 FL	*855.60 FL
20	1	*FRONT BONNET MOULDING	Not Necessary	336.80 FL	*- FL
21	2	*FRONT BONNET STOPPER	Not Necessary	48.40 FL	*- FL
22	1	*FRONT BONNET LOCK	Not Necessary	135.90 FL	*- FL
23	1	*FRONT WIPER PANEL GARNISH	N/S Cut	1,290.40 FL	*321.00 FL
24	1	*FRONT WIPER BLADE	Not Necessary	199.80 FL	*- FL
25	1	*FRONT WINDSCREEN GLASS	Cut	2,501.90 FL	*2,501.90 FL
26	1	*FRONT WINDSCREEN GLASS MOULDING	Necessary	66.30 FL	*66.30 FL
27	1	*FRONT SUPPORT PANEL	Buckled	1,561.20 FL	*1,360.00 FL
28	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	248.50 FL	*- FL
29	1	*FUSE BOX	Not Necessary	487.60 FL	*- FL
30	1	*FRONT FENDER LH	Distorted	1,312.50 FL	*1,312.50 FL
31	1	*FRONT FENDER EMBLEM HYBRID LH	Necessary	48.20 FL	*48.20 FL
32	1	*FRONT FENDER ANGLE VIEW MIRROR LH	Not Necessary	298.70 FL	*- FL
33	1	*FRONT FENDER COWLING LH	Deformed	259.30 FL	*259.30 FL
34	1	*FRONT FENDER INNER GARNISH LH	Not Necessary	123.20 FL	*- FL
35	1	*FRONT PILLAR QUARTER GLASS C/W MOULDING	Not Necessary	238.50 FL	*- FL
36	1	*FRONT FENDER SUPPORT BRACKET LH	Bent	85.20 FL	*85.20 FL
37	1	*FRONT RADAR SENSOR LH	Not Necessary	2,416.70 FL	*- FL
38	1	*FRONT WHEEL HOUSE PANEL LH	Repair	889.60 FL	*- FL
39	1	*FRONT ABS SENSOR LH	Not Necessary	543.90 FL	*- FL
40	1	*FRONT CROSSMEMBER	Not Necessary	2,704.80 FL	*- FL
41	1	*FRONT DRIVESHAFT	Not Necessary	1,534.80 FL	*- FL
42	1	*FRONT STEERING RACK & PINION	Bent	1,955.30 FL	*1,955.30 FL
43	1	*FRONT KNUCKLE ARM LH	Damaged	734.80 FL	*734.80 FL
44	1	*FRONT LOWER ARM LH	Bent	815.30 FL	*815.30 FL
45	1	*FRONT STABILIZER BAR LINK LH	Bent	165.20 FL	*165.20 FL
46	1	*FRONT SHOCK ABSORBER LH	Bent	519.10 FL	*519.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT WHEEL HUP C/W BEARING LH	Damaged	670.30 FL	*441.00 FL
48	2		*FRONT BONNET HINGE	Not Necessary	129.20 FL	*- FL
49	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
50	1		*SET FRONT GRILL CLIP	Necessary	80.00 FS	*30.00 FS
51	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
52	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*20.00 FS
53	1		*FRONT WINDSCREEN GLASS SOLAR FILM	Necessary	680.00 FS	*200.00 FS
54	1		*FRONT WINDSCREEN ERP BRACKET	Necessary	40.00 FS	*20.00 FS
55	1		*SET PRIVATE HIRER DECAL	Necessary	40.00 FS	*20.00 FS
56	1		*SET FRONT BONNET MOULDING CLIP	Not Necessary	50.00 FS	*- FS
57	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
58	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	120.00 FS	*- FS
59	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	60.00 FS	*- FS
60	1		*SET FRONT FENDER COWLING CLIP LH	Necessary	80.00 FS	*30.00 FS
61	1		*SET FRONT FENDER INNER GARNISH CLIP LH	Not Necessary	80.00 FS	*- FS
62	1		*SET FRONT FENDER LOWER GUARD CLIP LH	Not Necessary	80.00 FS	*- FS
63	1		*SET FRONT FENDER COWLING CLIPS	Necessary	80.00 FS	*30.00 FS
64	1		*FRONT PILLAR QUARTER GLASS SEALANR LH	Necessary	80.00 FS	*30.00 FS
65	1		*FRONT PILLAR QUARTER GLASS INNER SEAL LH	Necessary	60.00 FS	*30.00 FS
66	1		*FRONT PILLAR QUARTER GLASS SOLAR FILM LH	Not Necessary	250.00 FS	*- FS
67	1		*FRONT WHEEL TYRE LH	Punctured	680.00 FS	*350.00 FS
68	1		*SET FRONT WHEEL SPORT RIM	Cut	2,800.00 FS	*600.00 FS
69	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **46,390.11** **22,135.50**

- List Item Discount on L Items 25.00/25.00% (\$) 10,197.53 5,176.38

Total Parts (\$) **36,192.58** **16,959.12**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,000.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	250.00	30.00
5	REFOCUS HEADLAMP BEAM	New	80.00	0.00
6	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
7	REMOVE AND REFIX AND RESET FRONT SENSOR	New	80.00	50.00
8	REMOVE AND REFIX FRONT WINDSCREEN GLASS	New	150.00	120.00
9	TRANSFER FRONT QUARTER GLASS LH	New	100.00	60.00
10	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	850.00	220.00
11	FOUR WHEEL ALIGNMENT	New	120.00	80.00
12	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	380.00	0.00
13	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
14	SPECIAL COATING	New	888.00	400.00
15	RESET ABS LIGHT (NPA)	New	0.00	0.00
16	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	280.00	0.00
Gross Labour Cost (\$\$)			7,498.00	2,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >