

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|--------------------------------------|-----------------|--------------------------|--|
| | SOMPO INSURAN | ICE SINGAPORE PL | Ref: | CS3/SMO20008377/GKqf3e2- | |
| | 50 RAFFLES PLAC SINGAPORE LANI | CE #03-03 D TOWERSINGAPORE 048623 | Date: | 04/05/2021 | |
| | | | Code: | SMO | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | YN 633D | Veh. Inspected | SMC 8312C | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | CMTD2002356/GPL | Excess (\$) | 0.00 | |
| | Assign From | GNOH PAU LOONG | Assign Date | 10/03/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MERCEDES BENZ CLA180 | c.c | 1595 | |
| | Engine No. | HIDDEN | Year of Reg. | 2018 | |
| | Chassis No. | WDD1173422N681563 | Colour | WHITE | |
| | Odometer | 14732 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. | 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 225/40 R18 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 225/40 R18 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 225/40 R18 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 225/40 R18 | BRIDGESTONE | 6 mm | |
| 4. | . Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 12/08/2020 | Inspection Date | 13/08/2020 | |
| | Survey held at TEAM AUTOPRO PTE LTD | | | | |
| | 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722 | | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |
| | | | | | |