

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21003414/AND3E2

Date: 18/08/2022

REFERENCE

Insured/Claimant:	PREMIUM AUTOMOBILES PTE LTD	Policy No:	0999993762	
Date of Loss:	12/03/2021	Nature of Claim:	OD	Claim No: 3550904087SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ21T	Engine No:	CZS038885
Make & Model:	AUDI A8, 3.0 (A)	Chassis No:	WAUZZZF84LN009061
Reg. Date:	15/09/2020 (Man. Year: 2019)	Odometer:	3828 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$335,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35 R21	Rear Tyre Size:	275/35 R21
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	66,319.00	38,783.52	27,535.48	41.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,194.00	8,444.00	6,750.00	44.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	81,513.00	47,227.52	34,285.48	42.06
- Excess (S\$)	1,800.00	1,800.00	0.00	0.00
(S\$)	79,713.00	45,427.52	34,285.48	43.01
+ GST 7.00/7.00% (S\$)	5,579.91	3,179.93	2,399.98	43.01
Nett Amount (S\$)	85,292.91	48,607.45	36,685.46	43.01

INSPECTION

Date of Assignment:	16/03/2021		
Date Inspected:	13/03/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days		

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	3,540.00 FS	*2,832.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	526.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT - CENTER	Cracked	385.00 FS	*307.60 FS
4	1	*FRONT BUMPER CLOSING ELEMENT CAP - CENTER	Not Necessary	65.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT CAP - RH	Damaged	74.00 FS	*58.72 FS
6	1	*FRONT BUMPER LOWER INNER BRACKET - RH	Cracked	110.00 FS	*87.60 FS
7	1	*FRONT BUMPER LOWER CENTRE GRILLE	Cracked	466.00 FS	*372.80 FS
8	1	*FRONT BUMPER CHROME TRIM - RH	Cut	190.00 FS	*151.60 FS
9	1	*FRONT BUMPER CHROME TRIM CAP - RH	Necessary	16.00 FS	*12.56 FS
10	1	*FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	Missing	58.00 FS	*46.24 FS
11	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	591.00 FS	*472.80 FS
12	1	*FRONT BUMPER AIR GUIDE GRILLE TRIM - RH	Missing	220.00 FS	*175.60 FS
13	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	262.00 FS	*209.20 FS
14	1	*FRONT BUMPER LOWER SPOILER	Not Necessary	297.00 FS	*- FS
15	1	*FRONT BUMPER INNER BRACKET	Not Necessary	79.00 FS	*- FS
16	1	*RADIATOR GRILLE	Cracked	2,233.00 FS	*1,786.40 FS
17	1	*QUATTRO EMBLEM	Necessary	106.00 FS	*84.80 FS
18	1	*RADIATOR GRILLE EMBLEM COVER	Not Necessary	62.00 FS	*- FS
19	1	*RADIATOR GRILLE CAMERA COVER CAP	Not Necessary	136.00 FS	*- FS
20	1	*RADIATOR GRILLE CAMERA BRACKET	Not Necessary	48.00 FS	*- FS
21	2	*RADIATOR GRILLE END CAP - LH / RH	Not Necessary	46.00 FS	*- FS
22	1	*RADIATOR GRILLE CLOSING ELEMENT	Cracked	177.00 FS	*141.20 FS
23	1	*RADIATOR GRILLE AIR GUIDE - RH	Cracked	67.00 FS	*52.96 FS
24	2	*RADIATOR GRILLE SENSOR SUPPORT BRACKET - LH / RH	Not Necessary	102.00 FS	*- FS
25	1	*RADIATOR GRILLE LICENCE PLATE HOLDER	Cracked	828.00 FS	*662.40 FS
26	1	*FRONT 360 VIEW CAMERA	Not Necessary	906.00 FS	*- FS
27	1	*CONTROL UNIT FOR LASER DISTANCE CONTROL	Not Necessary	7,452.00 FS	*- FS
28	1	*DISTANCE SENSOR WATER JET	Not Necessary	107.00 FS	*- FS
29	1	*FRONT BUMPER REINFORCEMENT BEAM	Dented	1,253.00 FS	*1,002.40 FS
30	1	*FRONT BUMPER REINFORCEMENT BEAM FOAM FILLER	Cracked	127.00 FS	*101.20 FS
31	1	*FRONT BUMPER LOWER CROSS MEMBER	Bent	347.00 FS	*277.20 FS
32	1	*CROSS MEMBER REBOUND STRAP	Bent	79.00 FS	*62.96 FS
33	1	*CROSS MEMBER BRACE - LH / RH	O/S Bent	154.00 FS	*61.04 FS
34	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	60.00 FS	*- FS
35	1	*FRONT BUMPER SUPPORT - RH	Not Necessary	30.00 FS	*- FS
36	1	*FRONT BUMPER BRACKET - RH	Not Necessary	30.00 FS	*- FS
37	1	*FRONT BUMPER TOP COVER - SMALL	Not Necessary	35.00 FS	*- FS
38	1	*FRONT BUMPER TOP COVER - BIG	Not Necessary	199.00 FS	*- FS
39	1	*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	15.00 FS	*11.92 FS
40	1	*OUTSIDE TEMPERATURE SENSOR	Not Necessary	59.00 FS	*- FS
41	1	*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
42	1	*AIR CONDITIONER STICKER	Not Necessary	20.00 FS	*- FS
43	1	*RADAR SENSOR WITH CONTROL UNIT - RH	Cut	6,684.00 FS	*5,347.20 FS
44	1	*HORN - LOW TONE	Cracked	216.00 FS	*172.80 FS
45	1	*HORN BRACKET	Bent	47.00 FS	*37.28 FS
46	1	*HORN BRACKET	Bent	24.00 FS	*18.80 FS
47	1	*FRONT PARKING AID SENSOR - INNER (NPA)	Not Necessary	0.00 FS	*- FS
48	1	*FRONT PARKING AID SENSOR - OUTER (NPA)	Not Necessary	0.00 FS	*- FS
49	1	*FRONT PARK ASSIST SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
50	6	*FRONT PARKING SENSOR SEAL RING	Not Necessary	21.00 FS	*- FS
51	1	*SET FRONT BUMPER WIRING	Not Necessary	676.00 FS	*- FS
52	1	*FRONT FENDER - RH	Buckled	2,598.00 FS	*2,078.40 FS
53	1	*FRONT FENDER BRACE - RH FRONT	Bent	181.00 FS	*144.80 FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	1	*FRONT FENDER BRACKET - RH UPPER	Bent	46.00 FS	*36.24 FS
55	1	*FRONT FENDER GUIDE BRACKET - RH FRONT	Not Necessary	84.00 FS	*- FS
56	1	*FRONT FENDER BRACKET - RH LOWER	Not Necessary	32.00 FS	*- FS
57	1	*FRONT FENDER BRACE - RH INNER	Bent	539.00 FS	*431.20 FS
58	1	*FRONT FENDER BRACE - RH	Bent	152.00 FS	*121.60 FS
59	1	*FRONT FENDER BRACE RETAINING BRACKET - RH	Not Necessary	18.00 FS	*- FS
60	1	*FRONT WHEEL HOUSING LINER - RH	Not Necessary	422.00 FS	*- FS
61	1	*FRONT WHEEL SPOILER - RH	Cracked	95.00 FS	*75.60 FS
62	1	*FRONT WHEEL STONE CHIP GUARD - RH	Not Necessary	51.00 FS	*- FS
63	1	*BONNET	Dented	6,672.00 FS	*5,337.60 FS
64	1	*BONNET ATTACHMENT PARTS	Not Necessary	243.00 FS	*- FS
65	2	*BONNET HINGE - LH / RH	Not Necessary	542.00 FS	*- FS
66	1	*BONNET IMPACT PROTECTION - CENTER	Necessary	30.00 FS	*23.60 FS
67	2	*BONNET IMPACT PROTECTION - LH / RH	Necessary	40.00 FS	*30.56 FS
68	2	*BONNET HINGE PROTECTION - LH / RH	Necessary	22.00 FS	*16.64 FS
69	1	*FRONT FENDER COVER - RH	Not Necessary	78.00 FS	*- FS
70	1	*HEADLIGHT COVER - RH	Not Necessary	44.00 FS	*- FS
71	1	*FRONT FENDER COVER - RH	Not Necessary	36.00 FS	*- FS
72	1	*BONNET STRIKER - RH	Not Necessary	120.00 FS	*- FS
73	1	*BONNET LOCK WITH MICRO SWICTH	Not Necessary	214.00 FS	*- FS
74	1	*BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
75	1	*BOWDEN CABLE - CENTER	Not Necessary	58.00 FS	*- FS
76	1	*LED HEADLIGHT WITH MATRIX BEAM - RH	Cut	13,081.00 FS	*10,464.80 FS
77	1	*LIFT CYLINDER - RH	Not Necessary	272.00 FS	*- FS
78	1	*LIFT CYLINDER HOSE	Not Necessary	87.00 FS	*- FS
79	1	*LOCK CARRIER	Bent	1,389.00 FS	*1,111.20 FS
80	1	*LOCK CARRIER SUPPORT	Not Necessary	741.00 FS	*- FS
81	2	*LOCK CARRIER BRACE - LH / RH	Not Necessary	149.00 FS	*- FS
82	1	*PANHARD ROD	Not Necessary	155.00 FS	*- FS
83	2	*COOLANT REGULAR SUPPORT - LH / RH UPPER	Necessary	132.00 FS	*52.08 FS
84	2	*COOLANT REGULAR SUPPORT - LH / RH LOWER	Necessary	132.00 FS	*52.08 FS
85	1	*LOCK CARRIER SIDE SUPPORT LH	Not Necessary	402.00 FS	*- FS
86	1	*A/C CONDENSOR	Dented	952.00 FS	*761.60 FS
87	1	*CHARGE AIR COOLER RH	Dented	1,666.00 FS	*1,332.80 FS
88	1	*CHARGE AIR COOLER RH PRESSURE HOSE - RH LOWER	Not Necessary	460.00 FS	*- FS
89	1	*CHARGE AIR COOLER RH PRESSURE HOSE - RH UPPER	Not Necessary	303.00 FS	*- FS
90	1	*RADIATOR	Cracked	1,190.00 FS	*952.00 FS
91	4	*RADIATOR COOLANT	Necessary	179.00 FS	*143.04 FS
92	1	*RADIATOR AIR GUIDE - RH BIG	Cracked	36.00 FS	*28.40 FS
93	1	*RADIATOR AIR GUIDE - RH SMALL	Cracked	65.00 FS	*51.44 FS
94	1	*RADIATOR AIR DUCT - LOWER	Cracked	44.00 FS	*35.12 FS
95	1	*RADIATOR AIR DUCT - UPPER	Not Necessary	35.00 FS	*- FS
96	1	*ENGINE UNDERSHIELD	Not Necessary	755.00 FS	*- FS
97	1	*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
98	1	*SUNDRIES	Necessary	400.00 FS	*134.48 FS
99	1	*LOCK CARRIER CONNECTOR	Not Necessary	591.00 FS	*- FS
100	1	*FRONT BUMPER BRACKET - LH (Supplementary)	Not Necessary	30.00 FS	*- FS
101	1	*FRONT BUMPER SUPPORT - LH (Supplementary)	Not Necessary	30.00 FS	*- FS
102	1	*CENTER CLOSING ELEMENT COVER - LH (Supplementary)	Not Necessary	74.00 FS	*- FS
103	1	*AIR GUIDE GRILLE END CAP - LH (Supplementary)	Not Necessary	58.00 FS	*- FS
104	1	*AIR GUIDE GRILLE - LH (Supplementary)	Cracked	591.00 FS	*472.80 FS
105	1	*CENTER LOWER GRILLE AIR GUIDE - LH (Supplementary)	Not Necessary	67.00 FS	*- FS
106	1	*WATER JET BRACKET - RH (Supplementary)	Cracked	192.00 FS	*67.04 FS
107	1	*FRONT WHEEL SPOILER (Supplementary)	Cracked	95.00 FS	*75.60 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*RADIATOR CAP CLOSURE (Supplementary)	Necessary	22.00 FS	*17.52 FS
109	1		*CENTER CLOSING ELEMENT BRACKET - LH (Supplementary)	Not Necessary	110.00 FS	*- FS
110	1		*FRONT FENDER CHROME TRIM - RH (Supplementary)	Necessary	160.00 FS	*128.00 FS
F=Franchise part. S=SpcNett.				Total Parts (S\$)	66,319.00	38,783.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	450.00	300.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,000.00	3,600.00
5	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND RHS FRONT FENDER	New	4,000.00	1,800.00
6	TO RENEW FRONT BUMPER CONTROL UNIT FOR LASER DISTANCE CONTROL AND CONTROL UNIT FOR DISTANCE REGULATION FOR RADAR SENSOR	New	480.00	480.00
7	TO CARRY OUT PRE / POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			15,194.00	8,444.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >